

12/12/2020

REF: CS/AGI20010436/Gvd3

Special Instruction:

ASS. REC. BY:

Surveyor:

ASSIGNMENT (Office)

From (Person): STANLEY LAI

of

AGI

Date/Time: 29/9/2020@3.41PM

Estimated Cost:

Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 5997T

Insured: SLL 3282C

at Workshop m/s

THIAM HENG HUAT

Tel: 8263 6295

of

176 SIN MING DRIVE #05-14

Policy No:

Claim No: C10007421/LA

Sum Insured:

Excess:

D.O.A. 27/09/2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 3.57PM@29/9/2020 Person Contacted: STEVEN

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	REPAIRER AGREED SURVEY ON 30/9/2020
	SLT 5997T-
	SLL 3282C-
18/12/20	LS \$2550 confirmed by email (Red 22,989.90, 90%)