

12/02/2000

REF: CS3/MSG20010439/Gvd3 Special Instruction:

ASS. REC. BY:

SURVEY BY:

Merimen

ASSIGNMENT (Office)

From (Person): FIEVEL FOO

of MSIG

Date/Time: 29/09/2020@3.56PM

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBJ 6199U

Insured: GY 7678J

at Workshop m/s MHL AUTOMOBILE

Tel: 9653 3012

of BLK 3006 UBI ROAD 1# 01-360

Policy No: 1001439765

Claim No: 248135

Sum Insured:

Excess:

D.O.A. 28/09/2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

'WP'

H.O.D. Endorsement:

Date/Time 4.37PM@29/9/2020

Person Contacted:

GISON

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	REPAIRER AGREED SURVEY ON 30/9/2020
	GBJ 6199U- NA/INC20010415/z4 DOA :28/09/2020
	GY 7678J- NA/INC20010415/z4 DOA:28/09/2020
1/10/20	Submit PRS, repair range \$6,000-\$7,000 (6 days)