

ACC. REC. BY:

Steve

REF:

CS3/CT120010468/ESd3

ASSIGNMENT

From:

PRS

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	X	X	X
N/S	O/S		

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YP 6525H

Yr Regn:

1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Canter

c.c

2998

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

139279

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FEB 21 9A 20053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15C

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

26/9/20

D.O.I.

30/9/20

Survey held at

HSY Engineering

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA report

Repair range 15-16K

14 repair days

Date/Time, File Pass to?

05/10/2020

1) TYPIST

Date/Time, File Return to?

2)



Prell. Report



Final Report

Days Of Repair: 14

Resurvey No. of Trip: -

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Rep. Form:

PRS

Lump Sum / U.C. /