

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number: 68662672

Date Generated : 23/09/2020 User ID : JeongCH

	Section A - Accident	Details					
Registration Number	SG5535D						
Case Reference Number	BUS/09/20/5027						
Registration Date	12/19/2017						
Company Type	SMRT Buses Ltd						
Make	VOLVO						
Model	вэл						
Name of Driver	Wang Zhiyong						
Type of Accident	Head to Rear						
Accident Date and Time	9/19/2020 6:04 PM						
Accident Reported Date and Time	9/19/2020 7:28 PM						
Is Surveyor Required?	No						
Survey by							
Vehicle is Towed Back?	No						
Towed Back Date and Time							
Replacement Vehicle issued?	No	No					
Job Card Number	100						
Special Instruction to ARC, if any	SG5535D-REAR RIGHT PORTION GBD1192C (TP) INSURED WITH UNITED OVERSEAS						
Prepared Date and Time	9/23/2020 12:15 PM						
Chassis Number	YV3S4P925HA183736	vv3S4P925HA183736					
Mileage							
Work Shap	<u> </u>						
Repair Completion Date and Time							
	Santa B Comment of Bo	wate Entire store					
	Section B - Summary of Re	pair Estimates					
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable					
Total Labour Cost	\$1,060.00	\$0.00					
Total Spray Cost	5772.00	\$0.00					
Total Spare Part Cost	\$4,376.11	50.00					
Total Other Cost	\$0.00	50.00					
TOTAL COST	\$6,208.11 \$8,116.90	\$0.00					
Lump Sum Total	\$0.00	\$0.00					
Number of Repair Days	5.0						
Prepared / Adjusted By	Jeong Choon Hwee						
ARC / Surveyor Sign Off Date							
Signature	4	×					
Remarks							
	Section C - Quotation and Accid	lent Invoice Details					
Quotation Number	Invoice	Number					
Quotation Date	Invoice	Date					
Anoranou pare							



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4. Singapore 757705 FAX Number 63685592 Estimator Telephone Number . 68662623 Accident Reporting Number : 68662672

Date Generated: 23/09/2020

			Secti	on D - Deta	alls of Repair E	stimates				_
Part 1 - Labo	our Works									
Job Scope TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS		Quotation from AR \$1,060.00			Adjusted by Surveyor, if applicable					
Total Labour				\$1,060.00						
Part 2 - Spra	y Painting & P	anel Beating Rela	ited Works							1
Job Scope				Quotation from ARC			Adjusted by Surveyor, If applicable		7	
TO PUTTY & RESPRAY Total Spray Painting & Panel Beating			\$772.00				602			
			\$772.00							
Part 3 - Othe	r Costs - Acci	dent and Acciden	t Repair Related Expens							
lob Scope			Quotation from ARC			Adjusted by Surveyor, if applicable		1,66		
Total Other Co	osts									
Part 4 - Span	e Parts / Mater	fal Usage								
art Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
	+	- 	SMRT STICKER	1.00	\$75.00	0.00	\$75.00	Replace	Mec.	
		Lecle	SEALED LEVER LATCH	1.00	\$143.00	0.00	\$143.00	Replace	XSVC	
012130	ENGINE	A12-01979	O/S LOWER ENGINE	1.00	\$3,443.25	10.00	\$3,098.93	Replace	XSVC >	
012151	VE	ELU-00300	LIGHT, REVERSE LED, F OR VOLVO B9TL BUS	1.00	S647.08	10.00	\$582.37	Replace	/CR4	
012150	VE	ELU-00299	LIGHT, TAIL STOP, LED, F OR VOLVO B9TL BUS	1,00	\$519.83	10.00	\$467.85	Replace	/cnu	
	VE	ELU-00430	LAMP, RELECTOR: RED,F OR VOLVO B9TL BUS	1.00	\$9.95	10.00	\$8.96	Replace	/CRM] 1,134.1
5012147			F1111 EF11F SELF SEGGS		\$4,638.11		\$4,376.11] /
5012147 Cotal	1									¬
fotal	Parts / Materi	lal Usage After Su	rvevor Slaned off							i
otal Added Spare			rveyor Signed off		1.00	lar a co	les a notar es	lang chash	le	4
fotal	Portion	al Usage After Su Stock Number		Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	

botore. At puin pho

Sun Pin (Lick) 30/04/2000 TP with prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

1,134.18 1,868.79 4,664.97 P/P \$4,664.97 4days

Page 2 of 2

* EXT Rear O/S Corner * Light , Indicator : LED, For Volvo BATL Bus

\$1,440.94

\$467.85