

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
UNITED OVERSEAS INSURANCE LTD RO			Ref : CS/UOI20010474/Qsd3e2		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date: 18-11-2020 Code: UOI2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBD 1192C	Veh. Inspected	SG 5535D	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	M11D10882010	Excess (\$)	0.00	
	Assign From	JOSEPHINE WONG	Assign Date	30/09/2020	
2. Vehicle Particulars & Condition					
	Make & Model	VOLVO B9TL 9.4L AUTO	c.c	9364	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	YV3S4P925HA183736	Colour	MULTI COLOUR	
	Odometer	160241	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm	
	L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/09/2020	Inspection Date	30/09/2020	
	Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD				
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	!				