

Date: 2019, March
 Type: ☒ Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer
 Make: Audi A3
 Colour: Black
 Sp Reading: 9721
 Eng/No: WAUZZ28VXK1022681
 Gen Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt
 Modi: Nil / ☒ R/Rim / ☐ STD A/Rim or
 Tyre Size: F: 205/55R16, R: 205/55R16
 BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or
 Front R/Bal: 06 mm, Rear R/Bal: 06 mm
 Front L/Bal: 06 mm, Rear L/Bal: 06 mm
 D.O.A: 30/09/20
 Survey held at: Premium
 Des of Damages: Frl / Rear ☒ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision
 Vehicle: IN / OUT
 Date: Person Contacted:

Remark: The veh had commenced its repair at the time of inspection.

Excess: 600

N/S	O/S
-----	-----

Date / Time: Action / Instruction: OD ALG.

confirm repair cost of \$17,763.8 @ 13 days of repairs.
(RED: 7780.20 ;30%)

mv: 95k
 PV: 39.9k.
 Nett: 55.1k.

Date/Time: File For: ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 13
 Resurvey No. of Trip:

Site Insp: ☐
 Insp: ☐
 Insp: ☐

Survey Fee:
 Transportation:
 Fuel:
 Other: