

REC. BY: Ram

REF:

MSIG

PRS

ASSIGNMENT

From: _____ Date: 3.4.2020

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: PBF 1715

at Workshop m/s Global moto

of BIK 53 UB Dva 1 #01-12

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: ABN 11.00 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"up"

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBF 1715 Yr Regn: 30/12/2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda CBF 150 c.c. 149

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 087415 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LALKC11A7A3348040

Gen. Cond: Good (Fair) / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or Bt

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/80 R18

R: 90/90 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or DEERSTONE

Front

Rear

R/Bal. A mm R/Bal. S mm

L/Bal. - mm L/Bal. - mm

D.O.A. 29/03/2020 D.O.I. 3/04/2020

Survey held at Global motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range: \$1000-\$1500

Repair days: 4 repair days

STEVEN: 82884488

lump sum \$800, 4days

(red:1699;67%)

COR reviewed and amended.

MV: \$1200

PV: \$105

NV: \$1095/-

02/10/2020

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S+RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B./ (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Bike No. : FBF 171J

Date : 02-07-2020

2010

S/No.	Description	Price
1	Hand Lebar	\$ ✓ 78.00
2	Cone Bearing	\$ ✓ 80.00
3	Front Mudguard	\$ ✓ 78.00
4	Clutch Lever	\$ ✓ 28.00
5	Balancing One Set	\$ 30.00
6	Lamp Stand	\$ 95.00
7	Front Cover	\$ 150.00 100.00
8	Side Cover Left+Right	\$ 150.00 100.00
9	Exhaust Pipe	\$ 205.00
10	Talep Cover	\$ 180.00
11	Foot Rear Bracket	\$ 75.00
12	Front Fork One Set	\$ ✓ 160.00
13	Front Upper Bracket	\$ ✓ 130.00
14	Front Disc Wheel	\$ 120.00 100.00
15	Meter One Set	\$ 380.00
16	Box	\$ 180.00
17	Labour Charge	\$ 380.00

BT ✓

NEC ✓

BR ✓

Cut ✓

NEC ✓ Dem

NDX

Cut X Repair ✓

Cut X Repair ✓

X HU

X HU

X HU

BT ✓

NECV

NECV HU X

NDX

NDX

✓ 280 (-)

Sub Total \$ 2,499.00

TAMM Min

2/10/2020