

ORIGINAL

Vehicle No. SBX136S Date 2008 Sept.
 Type M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make Toyota Lexus GS300 cc 2995
 Colour Black A/C Insured / Std / Nil / NA
 Sp Reading 254425 T/Radio Insured / Std / Nil / NA
 Eng/Ho
 C/Ho JTHBH96S205062547
 Gen Cond Good / Fair / Poor / Burnt
 Steering In order / Jammed / Leaked / Burnt or
 Brake In order / Jammed / Leaked / Burnt or
 Modi Nil / S/Rim / STD A/Rim or
 Tyre Size F: 245/40R18
 R: 245/40R18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Habiband
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. 01/10/20
 Survey held at Tand C Automotive
 Des. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. Repairs 3 days Res. Yes or No
 Lmt. with % 3 Val Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted:

Date / Time Action / Instruction
TP AIG

COE Expiry: 14/09/28.

LS \$3900, 3 days. (Red \$8219.48, 68%)

MV
 PV
 Nett

Date/Time File Pass: ☐ Preli. Report
20/11 Typist ☐ Final Report
 Date/Time File Pass: ☐

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Site Insp

Interview

Test

MER-TP