

ASSIGNMENT

File No: _____ Date: _____

Insured Cos: _____

INSURANCE TYPE: RES / RES / EVA / INV / MV

INSURED VEHICLE NO: _____

STOPPAGE: _____

CLAIM NO: _____

CLASS: _____

STATUS: _____

Site Insured: _____ Excess: _____

Policy No: _____

Policy (Condition): _____

When the vehicle commenced its use: _____

When it was first used at the time of inspection: _____

Vehicle Value: 15K

Condition Report: _____ Consistent? : Yes or No

Condition Report: _____ Consistent? : Yes or No

Days of Repair: 3 days Res.: Yes or No

Days of Repair: _____ % Val.: Yes or No

CA: REV / REP. / 24 HRS

Person Contacted: _____ Vehicle: IN/OUT

N/S	O/S

Veh No: FBM 9517A Yr Regn: 26 MAY 2018

Type: M. Car / M. Cycle / BUS / Van / Lorry / Taxi / Private Motor / Truck / Tractor or _____

Make: YAMAHA XMAX 300 cc 292

Colour: GREY NO: Insured / Sid / Nil / (NA)

Sp. Reading: 23,712 TIRadp: Insured / Sid / Nil / (NA)

Engine No: _____

C/Nr: MH3540846JK003811

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Locked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Wash: Nil / S/Rim / STD / R/rin or _____

Tyre Size: F: 120 / 70 R15

R: 140 / 70 R14

BSI / DUNLOP / EXNOVA / GY / PS / LIZA / MIC / OITS / PIR / SUMITOMO / YOYO / YOKO or DUNLOP / BS (R)

Front: _____ Rear: _____

UBal: 3 mm UBal: 4 mm

DOB: _____

Survey held at: RICE PRODUCTION

Das. of Damages: Frt / Rear / O/S / HIS / UIC / Rocktop or _____

The UIC / Chassis frame / Body structure affected due to damage: _____

Days	Action / Instruction
1	COE Rebate \$5,439.00
2	Repair Limit \$9K. informed repairs. waiting for repair.
3	Repair cost based on marked estimate (excluding checked items) \$2,550.00

Days of Repair: _____

Resurvey No. of Trip: _____ Survey Fee: _____

Transportation: _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invo (\$ _____)

Weekend (\$ _____)

Report Format: _____

Limit Stat: 1.0, 1.5