Surveyor: NAZ | REF: MG

ASSIGNMENT

Date:

Veh No: FBM9517A Yr Regn: 26 MAY 2018

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: YAMAHA XMAX 300 cc 292

Colour: GREY A/C: Insured / Std / Nil / N/A

Sp.Reading: 23,712 T/Radio: Insured / Std / Nil / N/A

Eng/No:

Ch/No: M435H0846JK003811

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Wheel: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120 / 70 R15

R: 140 / 170 R14

BS / DUN / EXROVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or DUN(F), BS(R)

Excess: $300

N/S	O/S

Vehicle had commenced its journey at the time of inspection.

Estimated Value: 15K

Consistent? : Yes or No

Consistent? : Yes or No

Days: 3 days Res.: Yes or No

% Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Person Contacted:

Front: R/Bal. 3 mm L/Bal. - mm

Rear: R/Bal. 4 L/Bal. -

D.O.A.

Survey held at: RICE PRODUCTION

Date: 02/10/20

Dec. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body structure affected due to collision

MG L/S

Date / Time	Action / Instruction
	COE Rebate $5 439.00
	Repair Limit $9K. informed repairer. waiting for repair.
	Repair cost based on marked estimate (excluding checked items) $2,550.00

L/S $3700.00 (RED: $4433.00, 54%)

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation

Add Fee: Site Insp ($) Interview ($) Tech. Invs ($) Weekend ($)

Final Report

22/10/20 TYPIST

L/S $3700.00