

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

NTM (LIS)

Date: 01.10.2020
Time: 10:25:32
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305425539
REGN NO : SHA1152M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.01.2017
DATE/TIME IN : 30.09.2020 16:00
ACCIDENT DATE : 30.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	/	DET
0002 04-01-0103-2164-A	I40V3 GRILLE ASSY-RADIATO	1	1,480.00	20.00	1,184.00	/	DR
0003 04-01-0103-2175-G	I40V3 SYMBOL MARK-H	1	39.50	20.00	31.60	/	MC

SUB-TOTAL : 2,057.36

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 17-01	CHECK ALL LIGHTING	50.00	30

SUB-TOTAL : 650.00

TOTAL : 2,707.36

MVA NAME & SIGNATURE

DATE: 1/10/20

Steve (LKK) 83228813

SURVEYOR NAME & SIGNATURE

DATE: 1/10/20, 11.30am

WHL PngL

2 days

L/S

Ry AL SM

AUTHORISED : YES / NO

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: