



Your Ref: 17/18/20/VC11/315893

Date: 12th Nov 2020

Our Ref: CS1/LPM20010573/R1vf3e2

M/s Lonpac Insurance Bhd
21st Flr, Bangunan Public Bank
No. 6 Jalan Sultan Sulaiman
50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SDJ 2018L
INSURED VEHICLE: BPE 4084
ACCIDENT DATE: 30/05/2018**

We thank you for your instruction on 01/10/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDJ 2018L from M/s Cycle & Carriage Industries Pte Ltd.
- b) Singapore Accident Statement and Police Report of Vehicle SDJ 2018L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SDJ 2018L
Make & Model	: Mercedes Benz A200 FL Style (R17 HLG)
Year of Registration	: 2017
Chassis Number	: WDD1760432J501724
Engine Capacity	: 1595 cc

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.