

ASS. REC. BY:

REF: CS/MSG20010609/Uvf3

Special Instruction:

Surveyor: MARCUS ASSIGNMENT (Office)From (Person): CHHIA NYUK PIN of MSIG Date/Time: 02 Oct 2020 15:05

Estimated Cost: _____ Bill to: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CSTo Inspect Vehicle No: SLH 4108M Insured: SMM 1183Bat Workshop m/s Siang Hui Motor Works Tel: 67444605of 3006 Ubi Road 1, #01-338Policy No: A29128317AV2 Claim No: 629164

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27/09/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 2-10-20 4.15P.M Person Contacted: JIMMY Vehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	SLH 4108M- CC3/LCR17009615/K1za3q2 DOA :07/05/2017
	SMM 1183B- ☒
5/10/20	Informed Nyuk Pui pending estimate from repairer via merimen
8/10/20	Send IA via merimen