

ISS. REC. BY:

Z. J. M.

REF:

CC3/AH200/0643/Rida3

528A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDK 8531Bat Workshop m/s VOKSWAGENof ALEXANDRA RDInsured: AH

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 101K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDK 8531B Yr Regn: 2018 / PCBType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOKSWAGEN PASSAT 1.2 c.c 1197Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 37949 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVN222162JM564805

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45ZR18R: 235/45ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or .

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 28/09/2020D.O.I. 07/10/2020Survey held at VOKSWAGEN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s frt & o/s rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?



Prel. Report



Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.S. (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	528A

Vehicle No.:	SDK8531B
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Oct 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	BEETLE CABRIOLET 1.2 DSG
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CYV588384
Chassis No.:	WWZZZ16ZJM504805
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$24,301.00
Original Registration Date:	13 Feb 2018
First Registration Date:	13 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$26,022.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Feb 2028
PARF Rebate Amount:	\$19,516.00

COE Expiry Date:	12 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,000.00
COE Rebate Amount:	\$29,390.00
Total Rebate Amount:	\$18,906.00

The information contained herein is correct as at 07 Oct 2020

OK

CYV588384

t.com/used_cars/info.php?ID=899138&DL=3103

► Volkswagen Beetle Cabriolet 1.2A TSI

Overview

Financial

Accessories

Similar

Research

Photos

Map

Das WeltAuto.

Used cars you can trust. Guaranteed.

Price \$108,988**Depreciation** ? \$12,030 /yr
View models with similar depre**Reg Date** 27-Sep-2018
(7yrs 11mths 19days COE left)**Mileage** 13,350 km (6.6k /yr)**Manufactured** ? 2018**Road Tax** ? \$508 /yr**Transmission** Auto**Dereg Value** ? \$39,471 as of today (change)**OMV** ? \$24,316**COE** ? \$25,000**ARF** ? \$26,043**Engine Cap** 1,197 cc**Power** 77.0 kW (103 bhp)**Curb Weight** ? 1,421 kg**No. of Owners** ? 1**Type of Vehicle** Sports Car

Features

Iconic Beetle In Pristine Condition, Management Unit. Powerful And Fuel Efficient 1.2 TSI Engine With 7-speed

DSC

