



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20010651/UAYd3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 18-11-2020



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 7915E	Veh. Inspected	SLR 9327L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002892/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	05/10/2020

### 2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU11203012	Colour	RED
Odometer	233187	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	CROSSWIND	6 mm
L/H Front Tyre	225/50 R18	CROSSWIND	6 mm
R/H Rear Tyre	225/50 R18	ROADSTONE	6 mm
L/H Rear Tyre	225/50 R18	ROADSTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	02/10/2020	Inspection Date	05/10/2020
Survey held at	PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------