

Claim Handling

Task TransferExit

▼ Accident MT/1105642

LOS SAL SUB

Policy No.	5117729553	Vehicle No.	SFW2375M	GST Registration No.	
Certificate No.					
Policyholder Name	NG SWEE ENG			Policyholder NRIC	S1845542J
Product Code	PRIVATE CAR INSURANCE	Cover Type	drivo CLASSIC	Loading	0
Contact No.(Mobile)	97682713	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No

▼ Accident Details

Report Date	06/10/2020 09:16	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	04/10/2020	Time of Accident hh:mm	19:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTRE	Orange Force	No	ICM No.	
Accident Location	8 JLN KUBOR REST BUGIS HOTEL				

▼ Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	600.00	TP Standard Excess	0.00		
YIED OD Excess	500.00	YIED TP Excess	0.00	Driver is Covered?	Covered
Additional Excess	0.00				
Total OD Excess Applicable	1,100.00	Total TP Excess Applicable	0.00		

▼ Benefits

▼ GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

▼ Policyholder Mailing Address

Address 1	BLK 349 #08-1045	Address 2	UBI AVENUE 1	Address 3	SINGAPORE 400349
Address 4		Address Type	Singapore address	Post Code	400349
Unit No.		Related Policy Number	5117729553		

▼ OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	NG HON MUN (WU HANWEN)	Driver NRIC	S8718961I	Driver DOB	07/06/1987
Register Date of Driver License	18/06/2009	Driver Age	33	Driving Experience	11
Contact No.(Mobile)	87232418	Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 349 #08-1045	Address 2	UBI AVENUE 1	Address 3	SINGAPORE 400349
Address 4		Address Type	Singapore address	Post Code	400349
Unit No.	08-1045				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

▼ Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
Modification History			

▼ Investigation

Claim 002 OD-MD

▼ Claim Case Officer Tan Siew Choo

Claim Type	OD-MD	Insured Name	NG SWEE ENG	Insured NRIC	S1845542J
Contact No.(Mobile)	97682713	Contact No. (Home)	67463820	Contact No. (Office)	
Email Address	NG_SWEE_ENG@MOM.GOV.SG	OI Vehicle Number	SFW2375M	TP Vehicle Number	SHA4396G
Claim Description	SFW2375M / SHA4396G ON 4 Oct 2020			Name of Preferred Workshop	
Preferred Workshop Contact No.					
Preferred Repair Option	income to assign workshop	Insured Liability report	Partially Accepted		
Date Registered	06/10/2020 09:45	Claim Close Date		Date Received	06/10/20
Report Taken By	SHAN HUI	Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected by Workshop	
☒ Print AK letter					
Modification History					

▼ Special Claim Creation Approval

Approval

Reason

Remarks

damage assessment

Attachment

▼ Vehicle Info

Vehicle Make

NISSAN

Vehicle Model

SYLPHY

Engine Capacity

Date of Registration

24/06/2015

Classis No.

MNTBBAB17Z0023670

Towing Required *

☒ Yes

☐ No

Vehicle in IDAC *

☒ Yes

☐ No

Parallel Import *

☐ Yes

☒ No

Type of Tender *

Own Damage

Assessor Name *

BRYAN

Survey Current Status

IDAC/Workshop Name

NATIONAL ASSESSMENT CENTRE

IDAC/Workshop Location

51 UBI AVENUE 1 #01-25 PAYA

Windscreen Parts & Labour Cost

Total Loss *

☐ Yes

☒ No

Market Value(\$)

Scrape Value(\$)

Economical Repair Value(\$)

Remark

REMARK:NO OF REPAIR DAYS:6 DAYS.1X BOOTLID LOCK - REPLACE.1X BOOTLID LOWER CHROME MOULDING - REPLACE.1X REAR END PANEL - REPLACE.1X REAR END PANEL UNCONFIRM. 1X REAR BOOTLID WEATHER STRIPE - REPLACE.1X REAR LH BOOTLID LAMP - REPLACE.

Remark for Supplementary

▼ Damage Listing

Find a Part

root

Not Applicable

ABS

ABSORBER

ACCELERATOR

ACTUATOR

ADVERTISEMENT STICKER

AIR BAG

AIR BLOWER

AIR BOX

AIR CHAMBER BOX

AIR CLEANER

AIR COMPRESSOR

AIR CON

AIR CON (VAN)

AIR COOLER

AIR DISTRIBUTOR

AIR FILTER

AIR FLOW

AIR GRILLE

AIR HORN

No.	Part No.	Description	Qty *	Repair Cost
1	16000102	BUMPER (REAR)	1	Replace
2	16005104	BUMPER RETAINER (REAR RIGHT)	1	Replace
3	160053	BUMPER REVERSE SENSOR	1	Replace
4	16005902	BUMPER SPONGE (REAR)	1	Replace
5	150033	BOOT LID	1	Replace
6	150014	BOOT EMBLEM	3	Replace
7	25400106	FENDER (REAR RIGHT)	1	Replace
8	25400105	FENDER (REAR LEFT)	1	Replace
9	25401002	FENDER INNER TRIM (REAR RIGHT)	1	Replace
10	42000101	TAIL LAMP (LEFT)	1	Replace
11	42000102	TAIL LAMP (RIGHT)	1	Replace
12	16001304	BUMPER BRACKET (REAR RIGHT)	1	Replace
13	23300203	DOOR (REAR LEFT)	1	Repair
14	23300204	DOOR (REAR RIGHT)	1	Repair

Save

Submit