

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CC4/ASM20010676/Aps3q2	
	8 SHENTON WAY AXA TOWERSING		Date:	11/01/2021	
	ATTN:KHOR SAW	THENG	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SML 7305H	Veh. Inspected	GBG 8600E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S0M02UKX	Excess (\$)	0.00	
	Assign From		Assign Date	05/10/2020	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV350	c.c	2488	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JN1MC2E26Z0008530	Colour	SILVER	
	Odometer	60854 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	01/10/2020	Inspection Date	06/10/2020	
	Survey held at	SK AUTOMOBILE PTE LTD			
	23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
	•				