

Our Job Ref No : 30542196

Date 06/10/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr STEVE

Vehicle Reg No. SHA3463C

Date of Accident : 03/10/20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC GX5465A

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost**\$1,100.00**3. Estimated normal period for repairs: 2 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : _____

Name : _____

Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
ANNTENA ASSY-SMARTKEY ✓ BR	1	\$40.50	
			40.50
			-20%
			32.40
CHECK ITEM			
LABOUR			
TOTAL:		\$40.50	JUMANI