

ASS. REQ. BY:

REF:

CC4/FCI20010714/Rida3

490F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 5218A

at Workshop m/s BORNEO MOTOR

of 2, PANDAN CRESCENT

Insured: FCI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: _____

(Policy Condition)

2pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 160K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ 5218A Yr Regn: 2017, DKL

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA LEXUS RX200T LUX c.c 1998

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 47672 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTBAMCA402034218

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 233/55R20

R: n n

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or .

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 30/09/2020

D.O.I. 07/10/2020

Survey held at

BORNEO MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?



Prel. Report

1)

Date/Time, File Return to?



Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

\$ + RS. SI

Photos

Others

TOTAL

Rep Formet: _____

Lump Sum / L.S.A. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:

Singapore NRIC

Owner ID:

490F

Vehicle No.:

SLQ5218A

Vehicle to be Exported:

No

Intended Deregistration Date:

07 Oct 2020

Vehicle Make:

TOYOTA

Vehicle Model:

LEXUS RX200T LUXURY AT S/R

Primary Colour:

Black

Manufacturing Year:

2017

Engine No.:

8ARW617859

Chassis No.:

JTJBAMCA402034218

Maximum Power Output:

175.0 kW (234 bhp)

Open Market Value:

\$56,222.00

Original Registration Date:

15 Dec 2017

First Registration Date:

15 Dec 2017

Transfer Count:

0

Actual ARF Paid:

\$73,200.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

14 Dec 2027

PARF Rebate Amount:

\$54,900.00

COE Expiry Date:

14 Dec 2027

COE Category:

E - Open - all except motorcycle

COE Period(Years):

10

QP Paid:

\$54,334.00

COE Rebate Amount:

\$38,593.00

Total Rebate Amount:

\$93,493.00

The information contained herein is correct as at 07 Oct 2020

OK

► Lexus RX Turbo RX200t Luxury Sunroof

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

OMV/AUTO

Your Drive, Our Pride

Price	\$158,588		
Depreciation ⓘ	\$17,430 /yr View models with similar depre	Reg Date	06-Oct-2017 (6yrs 11mths 28days COE left)
Mileage	101,659 km (33.8k /yr)	Manufactured ⓘ	2017
Road Tax ⓘ	\$1,210 /yr	Transmission	Auto
Dereg Value ⓘ	\$89,864 as of today (change)	OMV ⓘ	\$56,222
COE ⓘ	\$50,000	ARF ⓘ	\$73,200
Engine Cap	1,998 cc	Power	175.0 kW (234 bhp)
Curb Weight ⓘ	2,070 kg	No. of Owners ⓘ	1
Type of Vehicle	SUV		

Features

2.0L Inline 4 Cylinders 16 Valve DOHC Twin-Scroll Turbocharged Engine Producing 234Bhp, 350Nm Of Torque. 6 Speed Automatic Transmission. View specs of the Lexus RX 300 (2015)

[Compare](#)