

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☐ S Rim / ☐ STD A/Rim or

Tyre Size:

F:

R:

BS / BH / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOTO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Date/Time. File Pass to?

1)

Date/Time. File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation.

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) \$ + RS \$

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

)

20/10/20 LTA # 2691 nett 8309

4/5 @ 4500 continued with Aln

16th Ticle

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

not Authorized
2/5 \$4500/
6/10/20
3 days.

VEHICLE No: AV 7297L

1PC	REAR SIGNAL LAMP O/S	130
1PC	REAR EXHAUST	
1PC	FRONT FOOTREST N/S	85
1PC	FRONT FOOTREST BRACKET N/S	166.00
1PC	GEAR LEVER	
1PC	SIDE STAND HOLDER	
1PC	SIDE STAND	
1PC	FRONT MIRROR N/S	
1PC	FRONT HAND GUARD N/S	
1PC	FRONT CLUTCH LEVER	115.00
1PC	FRONT BALANCER N/S	
1PC	HANDLE BAR	480
1PC	FRONT FORK ASSY N/S	
1PC	FRONT SPORT RIM	
1PC	HORN UNIT	
1PC	FRONT SIGNAL LAMP N/S	130
1PC	FRONT SIDE TOP GARNISH N/S	
1PC	FRONT FENDER	
1PC	FRONT FAIRING	

scr	\$152.00	✓
scr	\$920.00	X
scr	\$180.00	✓
scr	\$250.00	✓
scr	\$145.00	✓
scr	\$85.00	✓
scr	\$285.00	X
scr	\$145.00	✓
scr	\$285.00	✓
scr	\$145.00	✓
scr	\$60.00	✓
scr	\$645.00	✓
scr	\$1,050.00	X
scr	\$980.00	X
scr	\$285.00	✓
scr	\$150.00	✓
scr	\$380.00	✓
scr	\$350.00	X
scr	\$1,050.00	X
	\$7,542.00	

107

S.NETT

REAR GIVI SIDE BOX O/S	
REAR GIVI SIDE BOX BRACKET O/S	
REAR GIVI SIDE BOX N/S	
REAR GIVI TOP BOX	
REAR LICENCE PLATE	
FRONT SAFE GUARD BRACKET TOP N/S	
FRONT SAFE GUARD BRACKET BOTTOM N/S	

scr	\$980.00	450
scr	\$450.00	300
scr	\$980.00	450
scr	\$980.00	800
scr	\$20.00	12
scr	\$800.00	500
scr	\$600.00	300

TO REALIGN FRONT FORK	\$80.00	60
TO SPRAY PINTING	\$500.00	220
LABOUR FOR REPLACED PARTS	\$500.00	300

TOTAL \$13,432.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-2491
102
2241.9
5533.9
4507