

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR IN	SPECTION REPORT	
MS	MS FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI20010742/Etd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 09-11-2020		
			Code: FCI2	
1.		Policy Particular	s :- (THIRD PARTY CLAIM)	
	Insured Veh.	SHC 432B	Veh. Inspected	FBK 351E
	Policy No.		Coverage (\$)	0.00
	Claim No.	D20003965MFSH	Excess (\$)	0.00
	Assign From	MERINA CHIA	Assign Date	06/10/2020
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	HONDA	c.c	250
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	MLHMC41A2B5004304	Colour	BLACK
	Odometer	84104 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3.		Cond	litions of Tyres	
		Size	Make	Balance
		0.20		
	R/H Front Tyre	100/80-17	PIRELLI	4 mm
	R/H Front Tyre L/H Front Tyre			4 mm mm
				+
	L/H Front Tyre	100/80-17	PIRELLI	mm
4.	L/H Front Tyre R/H Rear Tyre	140/70-17	PIRELLI	mm 4 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	140/70-17	PIRELLI PIRELLI otion of Damages	mm 4 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SU	100/80-17  140/70-17  Description  STAINED DAMAGES AT THE CO	PIRELLI PIRELLI otion of Damages	mm 4 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SU	100/80-17  140/70-17  Description  STAINED DAMAGES AT THE CO	PIRELLI PIRELLI  ption of Damages  /S,N/S BODY AND FRONT	mm 4 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SU PORTION.	100/80-17  140/70-17  Description  STAINED DAMAGES AT THE Conception  Generally	PIRELLI  PIRELLI  ption of Damages  //S,N/S BODY AND FRONT  eral Information Inspect Date / Time	mm 4 mm mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SU PORTION.  Accident Date	100/80-17  140/70-17  Description  STAINED DAMAGES AT THE Concept of the concept	PIRELLI  PIRELLI  ption of Damages  //S,N/S BODY AND FRONT  eral Information Inspect Date / Time	mm 4 mm mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SUPORTION.  Accident Date Survey held at	100/80-17  140/70-17  Description  STAINED DAMAGES AT THE Control  General 28/09/2020  8 KAKI BUKIT AVENUE 4#03-	PIRELLI  PIRELLI  ption of Damages  //S,N/S BODY AND FRONT  eral Information Inspect Date / Time	mm 4 mm mm

Report Ref No. CS3/FCI20010742/Etd3e2

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

D)MARKET VALUE:\$5,500.00

**CHEN TSUE YEE** 

1

K.K.LAU CPT(RET)

**Automotive Assessor** 

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.