

Event

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle Ho

a Workshop m/s

of

Insured

Policy No

Claims No

Claim Insured

Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Mark. of Value

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs

days Res: Yes or No

Uninsured

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date

Person Contacted

Date / Time

Action / Instruction

TP QBE

MV

PV

Nett

Date/Time File Path to

☐

: Prel. Report

☐

: Final Report

If

Date/Time File Path to

If

Date/Time File Path to

Event No

GBJ2568P

or Regn: 2019 Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Nissan NV350

cc 2488

Colour

White

A/C: Insured / Std / NI / NA

Sp Reading

33/64

T/Radio: Insured / Std / NI / NA

Eng/Ho

C/Nr

JNM2E26Z0030862

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

195R15C

R:

195R15C

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

06

mm

R/Bal

06

mm

L/Bal

06

mm

L/Bal

06

mm

D.O.A

D.O.I

07/10/20

Survey held at

Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Days Of Repair:

Resurvey No. of Trips:

Survey Fee

Transportation

Site Fee

Other

Total

Total Fee:

☐

Site Insp

05

☐

Interview

05

☐

Final Rep

05

☐

Other

05