

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR INSF	PECTION REPORT	
AXA	A INSURANCE PTE LTD		Ref: CS3/ASM20010782/8	Eqf3e2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date: 09-10-2020	
1TTA	N : YVONNE ANG		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMV 9220C	Veh. Inspected	SMK 9996E
	Policy No.		Coverage (\$)	0.00
	Claim No.	S0M02UZB	Excess (\$)	0.00
	Assign From	YVONNE ANG	Assign Date	05/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN GOLF	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WVWZZZAUZFW358207	Colour	BLUE
	Odometer	82604 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	5 mm
	K/III TOILL Tyle			
	L/H Front Tyre	225/45 R17	MICHELIN	5 mm
	-	225/45 R17 225/45 R17	MICHELIN MICHELIN	5 mm 5 mm
	L/H Front Tyre			
4.	L/H Front Tyre R/H Rear Tyre	225/45 R17 225/45 R17	MICHELIN	5 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/45 R17 225/45 R17	MICHELIN MICHELIN on of Damages	5 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/45 R17 225/45 R17 Description STAINED DAMAGES AT THE FROM	MICHELIN MICHELIN on of Damages	5 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	225/45 R17 225/45 R17 Description STAINED DAMAGES AT THE FROM	MICHELIN MICHELIN on of Damages ONT N/S PORTION.	5 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	225/45 R17 225/45 R17 Descripti STAINED DAMAGES AT THE FRO	MICHELIN MICHELIN on of Damages ONT N/S PORTION. I Information Inspect Date / Time	5 mm 5 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	225/45 R17 225/45 R17 Description STAINED DAMAGES AT THE FROM Genera 03/10/2020	MICHELIN MICHELIN on of Damages ONT N/S PORTION. I Information Inspect Date / Time	5 mm 5 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS Accident Date Survey held at	225/45 R17 225/45 R17 Descripti STAINED DAMAGES AT THE FRO Genera 03/10/2020 Miracle Motorwerkz Pte Ltd-10 ka	MICHELIN MICHELIN on of Damages ONT N/S PORTION. I Information Inspect Date / Time	5 mm 5 mm
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS Accident Date Survey held at Repairer A) THE INSPECTION B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLI	225/45 R17 225/45 R17 Descripti STAINED DAMAGES AT THE FRO Genera 03/10/2020 Miracle Motorwerkz Pte Ltd-10 ka	MICHELIN MICHELIN on of Damages ONT N/S PORTION. I Information Inspect Date / Time ki bukit rd2#01-29 emarks THOUT PREJUDICE" BASIS. OAT THE TIME OF INSPECTION IMATE. PHOTOGRAPHS.	5 mm 5 mm 07/10/2020 (11:19 AM)

Report Ref No. CS3/ASM20010782/Eqf3e2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

6 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.