

Customer: NAZ REF: TMI

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
Type: M/Car / M/Cycle / BUS / Van / Truck / Taxi / Prime Mover /
Truck / Tractor or _____
To inspect Vehicle No: _____
Veh No: KE 3905 J Yr Regn: 26 DEC 2017
Type: M/Car / M/Cycle / BUS / Van / Truck / Taxi / Prime Mover /
Truck / Tractor or _____
Ins: MAN Lorry with MOBILE CRANE cc 10,518
Colour: WHITE A/C: Insured / N / I / A
Sp Reading: NA - Cylinders affected T/Radio: Insured / N / I / A
Eng/No: _____
Chassis: WMA375220HM729564
Gen. Cond. Good / Fair / Poor / Burnt
Steering: In order / Jammed / Locked / Burnt or
Brake: In order / Jammed / Locked / Burnt or
Wash: W / S / R / STD / A / R / I / or
Tire Size: F: 315 / 80 R 22.5
R: 11

Condition: _____
N/S O/S
When the vehicle had commenced its
repair at the time of inspection.
Condition? : Yes or No
Condition? : Yes or No
14 days Res.: Yes or No
3 Vol.: Yes or No
REV / REP / 24 HRS
Vehicle: OUT
Person Contacted: _____
Date: _____
Action/ Instruction
COF Rebate: \$30 291.00
Repair Limit: \$60K
Front: 4 mm Rear: 6 7
LBS: 4 mm LBS: 6 7
DOA: 30/9/2020 28 9/10/2020
Survey held at: ST Engineering
Des. of Damages: F / R / Rear / DIS / HIS / UIC / Noelap or
Interior burnt
The UIC / Chassis frame / body structure affected due to damage.

CHANGED REPAIRER TO LEE KUAN HWA

Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fee: _____
Transport: _____
Add Fee: ☐ Site Insp \$5
☐ Interview \$5
☐ Tech. Invo \$5
☐ Weekend \$5
Customer's Signature: _____
Inspector's Signature: _____
Lamin Sign: _____