

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Oct 2020 13:09 Sendback Est	07 Oct 2020 13:13 S\$1,930.70	08 Oct 2020 10:29 Edit Adj Rpt	S\$1,200.00 Edit Estimates	S\$1,200.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	GAIN CITY LOGISTICS PTE. LTD., Co. Reg. No.: 201508364R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHC2317M	Date of Loss:	07/10/2020 09:00 - :59 [36 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2004957	Policy/Cover Note No.:	MJ000019 (Comprehensive) Coverage: 23/01/2020 - 22/01/2021
Vehicle Reg. No. (Insured):	SKN1212U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 19/10/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SHC2317M (M2004957)
[SKN1212U]
TP
CTPL
Oct 7 2020 9:00AM
[GAIN CITY LOGISTICS PTE. LTD.]
ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	View View in Browser ▼	
Assessment Reports					1 per page ▼	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print	
1	07/10/20 13:13	Repairer Estimates		Load HTM		
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print	
1	08/10/20 10:30	Accident Statement From:SC - Reg. No: SKN1212U, Claimant: GAIN CITY LOGISTICS PTE LTD		Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	15/10/20 15:32	Adjuster Immediate Advice		Load HTM		
Photos/Images					3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	08/10/20 22:37	General View		Load JPG	☒	
2	08/10/20 22:37	General View		Load JPG	☒	
3	08/10/20 22:37	General View		Load JPG	☒	
4	08/10/20 22:37	Odometer Reading		Load JPG	☒	
5	08/10/20 22:37	Chassis Number		Load JPG	☒	
6	08/10/20 22:37	General View		Load JPG	☒	
7	08/10/20 22:37	General View		Load JPG	☒	
8	08/10/20 22:37	General View		Load JPG	☒	
9	08/10/20 22:37	General View		Load JPG	☒	
10	08/10/20 22:37	General View		Load JPG	☒	
11	08/10/20 22:37	General View		Load JPG	☒	
12	08/10/20 22:37	General View		Load JPG	☒	
13	08/10/20 22:37	General View		Load JPG	☒	
14	08/10/20 22:37	General View		Load JPG	☒	
15	08/10/20 22:37	General View		Load JPG	☒	
16	08/10/20 22:37	General View		Load JPG	☒	
17	08/10/20 22:37	General View		Load JPG	☒	
18	08/10/20 22:37	General View		Load JPG	☒	
19	08/10/20 22:37	General View		Load JPG	☒	
20	08/10/20 22:38	Photo After Spray		Load JPG	☒	
21	08/10/20 22:38	Photo After Spray		Load JPG	☒	
22	08/10/20 22:38	Photo After Spray		Load JPG	☒	
Documentation					1 per page ▼	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail	Print	
1	16/10/20 13:55	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee		Load PDF		
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print	
1	07/10/20 13:14	E-filed GIA report		Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI20010810/EYD3S2**Date:** 20/10/2020REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MJ000019

Claimant Vehicle No : SHC2317M**Insured Vehicle No :** SKN1212U

Date of Loss: 07/10/2020

Nature of Claim: TP

Claim No: M2004957

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC2317M**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No: 2ZRS066685

Reg. Date: 03/10/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU903565148

Colour: Blue

Odometer: 333889 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

Good

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,199.70	960.60	239.10	19.93
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	720.00	550.00	170.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	1,930.70	1,521.60	409.10	21.19
Approved Total (Overridden) (\$\$)		1,200.00		
(\$\$)	1,930.70	1,200.00	730.70	37.85
+ GST 7.00/7.00% (\$\$)	135.15	84.00	51.15	37.85
Nett Amount (\$\$)	2,065.85	1,284.00	781.85	37.85

INSPECTION

Date of Assignment: 08/10/2020 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 07/10/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** YVONNE WONG YIN CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

10/20/2020

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Oct 2020)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC2317M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Dented	458.60 FL	-	*458.60 FL
2	1		*REAR BUMPER CENTER-BLACK	Cut	552.60 FL	-	*552.60 FL
3	1		*REAR BUMPER REINFORCMENT	Not Necessary	318.80 FL	-	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
5	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 F
6	1		*REVERSE SENSOR	Shorted	135.70 F	-	*135.70 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,537.70	1,218.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	338.00	258.30
Total Parts (\$\$)	1,199.70	960.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING	New	250.00	200.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			720.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >