

						ENGINEERING		
Our Job Ref No 305426685								
Date : 9. Oct. 2020						ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FINA	LIZAT	ION FORM				Fax:	6546 8156	
To : <b>LKK</b>						Fax :		
Attn	tn ; STEVE							
Vehic	cle Reg	No. : SHC	2059H		Dat	e of Accident:	3. Oct. 2020	
The s	survey	and estimates of	the repairs of the	above-mentio	ned vehicle ar	e as follows:-		
1.	The repair job shall bill to:			NTUC			FBP3998T	
2.	The finalized amount shall be:							
	(a) Spare Parts after List discount							
	(b) Labour Charges							
	Total for Part-By-Part Repair Cost						\	
	(c.)	Lumpsum Repa Total for Lumps Final Lumpsur	um repair cost aft	er Less:	20%	-	\$1,350.00	
3. 4.	Estimated normal period for repairs: 2  We shall treat the above amount as Correct and Confi working days				*	working days.  med if there is no reply from you within 7		
5.		k you for your ass	sistance.	We confirm the estimates and finalized amount				
	Signature:				Sig			
	Name : Loke Wei Yieng				_ Na	Name :		
	Tel : 6214 8316				Date :			
	Fax	6546 815	6		=:			
For O	fficial	Use Only						
	Item Am			unt	Document Attached Yes or No	Confirm By (Signature)	Remarks	
Rental Rate P/Day					YES			
2. Loss of Income Paid					NO			
3. Su	rvey F	ees						
LTA Search Fee     Medical Fees (on behalf of driver, if applicable)     Overrun			\$7.49 / \$	\$2.00				
o Uv	errun						0	
Rema	rks:							