

ASS. REC. BY:

REF: CS/MSG20010820/Ktf3

Special Instruction:

Surveyor: KENNETH ASSIGNMENT (Office)From (Person): Monica Chung of MSIG Date/Time: 07 Oct 2020 16:14

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMR 2770Z Insured: SLU 3553Zat Workshop m/s MBM Wheelpower Pte Ltd Tel: 6262 8888of 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin MingPolicy No: 29138106AL2 Claim No: 629511

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06/10/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 7-10-20 4.33P.M Person Contacted: SHIRLEY Vehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	INSP:160 Sin Ming Drive #06-02, Sin Ming AutoCity,
	SMR 2770Z- ☒
	SLU 3553Z- ☒