

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SCK 91T Ref: CC4/ASM200 Date: 15/04/2021 Code: ASM Veh. Inspected SMG 8645X	10827/Bpa3q2	
AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG Code: ASM Policy Particulars :- THIRD PARTY CLAIM		
1. Policy Particulars :- THIRD PARTY CLAIM		
Insured Veh. SCK 91T Veh. Inspected SMG 8645X		
Policy No. GA520025/1 Coverage (\$) 0.00		
Claim No. \$0M02V2K Excess (\$) 0.00		
Assign From Assign Date 07/10/2020		
2. Vehicle Particulars & Condition		
Make & Model HONDA SHUTTLE HYBRID c.c 1496		
Engine No. HIDDEN Year of Reg. 2019		
Chassis No. GP72002095 Colour RED		
Odometer 27772 KM Steering IN ORDER		
Brakes IN ORDER Modification SPORTS RIM	I	
General FAIR		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre 185/60 R15 YOKOHAMA 5 mm		
L/H Front Tyre 185/60 R15 YOKOHAMA 5 mm		
R/H Rear Tyre 185/60 R15 YOKOHAMA 5 mm		
L/H Rear Tyre 185/60 R15 YOKOHAMA 5 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 07/10/2020 Inspection Date 08/10/2020		
Survey held at TEAM AUTOPRO PTE LTD		
160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days		