

ASS. REC. BY: Pam


REF: CS/CT120010830/R19f3

594W

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMJ 29925
 at Workshop m/s PERFORMANCE
 of 303, MELANDEA RD
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 122K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMJ 29925 Yr Regn: 2019 / FEB
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: B.M.W XI DRIVE 18160 c.c. 1499
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp. Reading: 15493 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBAJH12010ENS1928
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or _____
 Brake: Order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/50R18
 R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 05/10/2020 D.O.I. 19/10/2020
 Survey held at PERFORMANCE
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Rep. Format: _____

Lump Sum / B.B. (\$): _____

Survey & Repair
19/10 @ 10am



Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

07 OCT 2020

ESTIMATE

Estimate No. : b1 56221	Page No. : 1 of 5
Date Estimated : 07/10/2020	
Prepared By : Inthiran A/L Thurasamy	
- ESTIMATE REPAIR FOR - MEPO CONCEPT PTE LTD 13 SEA BREEZE ROAD Singapore 487484	- ACCOUNT - 135 China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMJ2992S	WBAJG12010EN51928	28/02/2019	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper, tailgate, attachments and repair tail panel.

2550 3,400.00

To painting rear bumper, taigate and tail panel.

2467 2,742.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 531.00

To replace bootlid smart opener control unit, top and bottom sensor lines including program and conduct checks for proper function.

561? 661.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries

? 150.00

Total Labour 1: 8,227.00

DESCRIPTION	QTY	PRIC	VALUE
BLIND RIVET NUT M6	4	2.70	10.80
BOOTLID	1	1,236.65	1,236.65
RR BUMPER CARRIER	1	496.35	496.35
MOUNTING SMART OPENER	1	45.55	45.55

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 56221
Date Estimated : 07/10/2020
Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMJ2992S	WBAJG12010EN51928	28/02/2019	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
REAR TRIM UNDERRIDE PROTECTION (X L <i>scr</i>)	1	190.80	190.80
RR BUMPER LH CORNER MOUNTING	1	142.65	142.65
RR BUMPER RH CORNER MOUNTING	1	142.65	142.65
REAR BUMPER PANEL PRIMED <i>de</i>	1	903.40	903.40
REAR BUMPER MIDDLE TRIM PANEL (PDC) <i>de</i>	1	265.65	265.65
REAR BUMPER TRIM BOTTOM (LINES) <i>de</i>	1	232.45	232.45
EMBLEM GROMMET <i>re</i>	2	0.85	1.70
BMW PLAQUE WITH ADHESIVE FILM <i>re</i>	1	71.60	71.60
LETTERING S DRIVE 18i <i>re</i>	1	96.65	96.65
LETTERING X1 <i>re</i>	1	64.45	64.45
REAR BUMPER HEAT INSULATION	1	69.85	69.85
PLUG BLACK D=5MM	7	0.95	6.65
SENSOR WIRE FOR SMART OPENER TOP	1	46.30	46.30
SENSOR WIRE FOR SMART OPENER BOTTOM	1	50.90	50.90
ULTRASONIC SENSOR BLACK <i>re</i>	2	249.95	499.90
DECOUPLING RING PDC TORQUE CONVERTER <i>re</i>	2	5.10	10.20
(DG) CLEANER R1 (100ML) <i>re</i>	1	26.15	26.15
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>re</i>	1	27.85	27.85
Total Parts :			4,639.15

No. of Working Days Recommend	Surveyor's E-mail
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No	PML Yes / No
Authorised Date	Time
Surveyor's Tel	Authorised Yes / No
Surveyor's Name	Sign
Date & Time	Value \$
Regn No.	
Claims OD / 3rd Party	

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No.	Claim No.
Date & Time 19/10/2020 11:30	Excess \$
Surveyor's Name <i>Pran</i>	Sign
Surveyor's Tel 90210268	Authorised Yes / No
Authorised Date	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No	PML Yes / No
Surveyor's E-mail	
No. of Working Days Recommend 7 days	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Labour 1	:	8,227.00
Parts	:	4,639.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	900.63
Grand Total	:	13,766.78

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Date Of Report 05/10/2020 18:12
Date Of Accident 05/10/2020 13:15
Exact Location Of Accident BEDOK SOUTH AVE 1
Country/State of Loss SINGAPORE

Vehicle Registration Number SMJ2992S

Insured/Policyholder

Name Of Registered Owner MEPO CONCEPT PTE LTD
Co Reg No 2XXXXX594W
Email Address KYEAN.LEE@HOTMAIL.COM
Mobile Phone No (LOCAL) +65-97386236
Alternative Phone No OFFICE-97386236

Vehicle Particulars

Manufacturer BMW
Model X1
Exact Purpose for which vehicle was being used at time of accident NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company LIBERTY INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number UNAVAILABLE
Cover Note Number

Driver

Name of Driver GAO ZI QI
NRIC No SXXXX696A
Date Of Birth 18/03/1981
Occupation INDOOR
Date Of Driving Pass 10/08/2005
Driving Experience 15 YEARS AND 1 MONTH
Gender FEMALE
Mobile Number (LOCAL) +65-91834529
Fax Number (LOCAL) +65-97386236
Contact Number
EMail Address SALES@MEPOCONCEPT.COM

Address 215 BEDOK SOUTH AVE 1 #03-09
 Postcode 469338
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

!! DETAILS OF OTHER VEHICLE PROPERTY !!

Vehicle Registration Number SMK7082E
 Vehicle Make/Model/Colour HONDA
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LIN HOCK LIM
 NRIC/Passport Number SXXXX579B
 Contact Number 90233474
 Address BLK 211B COMPASSVALE LANE #08-208
 Postcode 542211
 Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Nature Of Damage FRONT
 No. Of Passenger (Including Driver) 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

5/10/2020

5:02pm




Driver's Signature
(If driver is not the policyholder)
Date & Time:

5/10/2020


5:02pm

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:



SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

my ^{was} ~~car~~ waiting for turn and suddenly a vehicle (registered plate No SMK7082E) crashed into my car at the back/rear.

DECLARATION


I/We declare the foregoing particulars are true in every respect.




Policyholder's Signature
Date & Time:

5/10/2020

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre:  Personal's Signature

Name: 
NRIC/FIN No.:
Performance Motors Limited
303 Alexandra Road
Sims Darby Performance Centre
Singapore 119975

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Company
Owner ID: 594W

Vehicle No.: SMJ2992S
Vehicle to be Exported: No
Intended Deregistration Date: 19 Oct 2020
Vehicle Make: B.M.W.
Vehicle Model: X1 SDRIVE 18I LED NAV
Primary Colour: Brown
Manufacturing Year: 2018
Engine No.: 38545550B38B15A
Chassis No.: WBAJG12010EN51928
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$36,399.00
Original Registration Date: 28 Feb 2019
First Registration Date: 28 Feb 2019
Transfer Count: 0
Actual ARF Paid: \$42,959.00

Intended PARF Rebate Profile
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Feb 2029
PARF Rebate Amount: \$32,219.00

Intended COE Rebate Profile
COE Expiry Date: 27 Feb 2029
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$35,403.00
COE Rebate Amount: \$29,586.00
Total Rebate Amount: \$61,805.00

The information contained herein is correct as at 19 Oct 2020

OK

Brown



Merimen e-Claims



Used 2019 BMW X1 sDrive18i for



PARF/C

mart.com/used_cars/info.php?ID=934732&DL=2351

▶ BMW X1 sDrive18i

Overview

Financial

Accessories

Similar

Research

Photos

Map



PERFORMANCE PREMIUM SELECTION LIMITED

Price \$121,800**Depreciation** ⓘ \$12,210 /yr
View models with similar depre**Reg Date** 29-Jan-2019
(8yrs 3mths 9days COE left)**Mileage** 40,711 km (23.6k /yr)**Manufactured** ⓘ 2018**Road Tax** ⓘ \$684 /yr**Transmission** Auto**Dereg Value** ⓘ \$59,136 as of today (change)**OMV** ⓘ \$35,224**COE** ⓘ \$33,989**ARF** ⓘ \$41,314**Engine Cap** 1,499 cc**Power** 103.0 kW (138 bhp)**Curb Weight** ⓘ 1,430 kg**No. of Owners** ⓘ 1**Type of Vehicle** SUV

Features

BMW TwinPower Turbo 3 Cylinder Engine With 136bhp, 220Nm Of Torque. 0-100km/h In 9.7s, Top Speed 200km/h, 7 Speed Transmission DCT, Front Wheel Drive. View specs of the BMW X1

