

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CG / A16200128344es3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGS 21343

Yr Regn:

3 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make:

Mudra stream

C.C.

1799

Colour:

S.hu

A/C:

Insured / Std / NI / NA

Sp. Reading

147114

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RW61021149

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65-215

R:

Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

3/10/20

D.O.I.

8/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Loc 6-3-2027 47A#32267

no BI involved Net#9733

30/04/20 4/5#3200 Confirmed w. the Alan.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) ___\$ + RS ___\$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

LKK: Asker

Not Authorized
LKK
1/5 3200/
3 days.

VEHICLE No: SGS 2134B

1PC	FRONT DOOR O/S	845-20	Body	\$1,120.20 ✓
1PC	FRONT DOOR HINGE O/S		Seat	\$165.00 ✓
1PC	FRONT DOOR CHECKER O/S		Trm	\$188.20 ✓
1PC	FRONT DOOR MIRROR O/S		R	\$485.20 X
1SET	FRONT DOOR FRAME BLACK STICKER O/S		rel	\$80.00 ✓
1PC	FRONT DOOR OUTER HANDLE O/S	245-50	rud/cra	\$366.20 ✓
1PC	FRONT DOOR OUTER GLASS MOULDING O/S		Seat	\$165.50 ✓
1PC	FRONT DOOR GLASS REGULATOR O/S	215-20	Seat	\$322.50 ✓
1PC	FRONT DOOR GLASS REGULATOR MOTOR O/S	422-30	shut/d	\$450.50 ✓
1PC	FRONT DOOR INNER TRIM BOARD O/S	488-20	de/cra	\$655.20 ✓
1SET	FRONT DOOR INNER TRIM BOARD CLIPS O/S		rel	\$50.00 ✓
1PC	FRONT DOOR INNER RUBBER O/S		rel/trm	\$185.20 ✓
1PC	FRONT DOOR INNER RUBBER CHANNEL O/S		rel/trm	\$228.20 ✓
1PC	REAR DOOR O/S		R	\$1,005.20 X
1PC	ROCKER PANEL O/S		R	\$655.50 X
				\$6,122.60

20%

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$50.00	30
TO TRANSFER FRONT DOOR MECHANISM	\$80.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	480
TO PUTTY & SPRAY PAINTING	\$1,080.00	800
TOTAL	\$8,302.60	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-3278-10
20%
2622-80
4012-80
3210.