



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : GBH1478D

JOB NO. : _____

8535.00

ESTIMATE REPORT 1st QUOTATION

OWNER'S PARTICULAR

NAME : CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
ADDRESS :

CONTACT :

VEHICLE NO YP6815X TRANS.
MAKE / MODEL : ISUZU LORRY
OWNER'S INSURER FIRST CAPITAL
JOB-CODE : TP S/A : MICHELLE

CHASSIS NO :

ENGINE NO :

ACCIDENT DATE : 27-Sep-20

CLAIM DETAIL

MATERIALS

- 1 TAILLAMP ASSY LH
- 2 TAILLAMP ASSY RH
- 3 REAR AXLE
- 4 REAR MUDFLAP LH
- 5 REAR MUDFLAP RH
- 6 REAR MUDFLAP BRACKET INNER LH
- 7 REAR MUDFLAP BRACKET INNER RH
- 8 REAR MUDFLAP BRACKET OUTER LH
- 9 REAR MUDFLAP BRACKET OUTER RH
- 10 REAR MUDFLAP LOWER RUBBER - ISUZU LH
- 11 REAR MUDFLAP LOWER RUBBER - ISUZU RH
- 12 CRANE BRACKET RH
- 13 CRANE BRACKET LH
- 14 REAR CRANE FORK ASSY *Pr?* 4200 SN
- 15 REAR NO PLATE LAMP
- 16 REAR NO PLATE LAMP BRACKET

	QTY	QUO-PRICE	DISC %	DISC-PRICE	SUR-DISP	REV. PRICE
<i>Sn</i>	1.00	\$ 450.00	10.00	\$ 405.00	Y	X
<i>Sn</i>	1.00	\$ 450.00	10.00	\$ 405.00	Y	X
<i>Sn</i>	1.00	\$ 13,500.00	10.00	\$ 12,150.00	Y	X
<i>Sn</i>	1.00	\$ 520.00	10.00	\$ 468.00	Y	X
<i>Sn</i>	1.00	\$ 520.00	10.00	\$ 468.00	Y	X
<i>R</i>	1.00	\$ 220.00	10.00	\$ 198.00	Y	X
<i>R</i>	1.00	\$ 220.00	10.00	\$ 198.00	Y	X
<i>R</i>	1.00	\$ 220.00	10.00	\$ 198.00	Y	X
<i>R</i>	1.00	\$ 220.00	10.00	\$ 198.00	Y	X
<i>Sn</i>	1.00	\$ 180.00	10.00	\$ 162.00	Y	X
<i>Sn</i>	1.00	\$ 180.00	10.00	\$ 162.00	Y	X
<i>R</i>	1.00	\$ 2,200.00	10.00	\$ 1,980.00	Y	X
<i>R</i>	1.00	\$ 2,200.00	10.00	\$ 1,980.00	Y	X
<i>R</i>	1.00	\$ 16,000.00	10.00	\$ 14,400.00	Y	X
<i>Sn</i>	1.00	\$ 105.00	10.00	\$ 94.50	Y	X
<i>R</i>	1.00	\$ 250.00	10.00	\$ 225.00	Y	X

TOTAL (PARTS) :

\$ 37,435.00

\$ 33,691.50

SPECIAL NETT ITEM

- 1 REAR CABIN TAILLAMP PANEL LH
- 2 REAR CABIN TAILLAMP PANEL RH
- 3 REAR STICKER 60KM
- 4 REAR REFLECTOR STICKER - RED
- 5 REAR REFLECTOR STICKER SIDE RH- BLUE & ORANGE
- 6 REVERSE CAMERA
- 7 REAR CRANE
- 8 REAR CRANE FORK
- 9 EXHAUST SILENCER
- 10 REAR NUMBER PLATE
- 11 REAR NUMBER PLATE BRACKET
- 12 CONE BRACKET X2

<i>R</i>	1.00	\$ 680.00	0.00	\$ 680.00	Y	X
<i>R</i>	1.00	\$ 680.00	0.00	\$ 680.00	Y	X
<i>NN</i>	1.00	\$ 30.00	0.00	\$ 30.00	Y	X
<i>NN</i>	1.00	\$ 180.00	0.00	\$ 180.00	Y	X
<i>NN</i>	1.00	\$ 360.00	0.00	\$ 360.00	Y	X
<i>Sn</i>	1.00	\$ 380.00	0.00	\$ 380.00	Y	X
<i>R</i>	1.00	\$ 9,500.00	0.00	\$ 9,500.00	Y	X
<i>R</i>	1.00	\$ 2,800.00	0.00	\$ 2,800.00	Y	X
<i>R</i>	1.00	\$ 1,900.00	0.00	\$ 1,900.00	Y	X
<i>Sn</i>	1.00	\$ 50.00	0.00	\$ 50.00	Y	X
<i>R</i>	1.00	\$ 150.00	0.00	\$ 150.00	Y	X
<i>R</i>	2.00	\$ 600.00	0.00	\$ 600.00	Y	X

TOTAL (PARTS) :

\$ 17,310.00

\$ 17,310.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00	\$ 2,000.00	0.00	\$ 2,000.00	Y	1000L	
2	SPRAY PAINTING ON ACCIDENT AREA	1.00	\$ 1,800.00	0.00	\$ 1,800.00	Y	400L	
3	R&R CRANE TO SERVICE TO LIFT UP & DOWN	nn	1.00	\$ 480.00	0.00	\$ 480.00	Y	X
4	R&R REAR SUSPENSION LH	nn	1.00	\$ 380.00	0.00	\$ 380.00	Y	X
5	CHECK & REPAIR WIRING SYSTEM	1.00	\$ 80.00	0.00	\$ 80.00	Y	15L	
6	RESPRAY TUFF KOTE ON AFFECTED AREA	nn	1.00	\$ 120.00	0.00	\$ 120.00	Y	X
7	CONDUCT CHASSIC REPAIR REAR LH PORTION	nn	1.00	\$ 1,200.00	0.00	\$ 1,200.00	Y	X
8	R&R REAR AXLE, AXLE SPRING & LONG SHAFT TO ASSIT REPAIR	nn	1.00	\$ 900.00	0.00	\$ 900.00	Y	X
9	RESET & PROGRAMME LTA SYSTEM & INSPECTION	nn	1.00	\$ 980.00	0.00	\$ 980.00	Y	X
10	POST ACCIDENT REPAIR INSPECTION	1.00	\$ 180.00	0.00	\$ 180.00	Y	720L	

TOTAL (LABOUR) :

\$ 8,120.00

\$ 8,120.00

TOTAL PARTS & LABOUR

\$ 62,865.00

\$ 59,121.50

EXCESS : : \$S _____

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$S _____

DATE OF SURVEY : ____/____/____

SURVEY BY : _____

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____