

7205/2003

ASS. REC. BY:

REF: CS3/III20000740/R1vd3 Special Instruction:

08/10/2020

Signature: RASU

merimen

CARINE KHEK

ASSIGNMENT (Office)

From (Person): Gabriel Wee

of

III

Date/Time:

13/01/2020 @ 11am

Estimated Cost:

Bill to:

Out: TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JTL 1549

Insured:

SHA 20855

at Workshop m/s

Hua chin

Tel:

9855 2631

of

50 Bukit Batok Street 23 # 02-02

Policy No:

MCOM0015

Claim No:

MCT19120283

Sum Insured:

Excess:

D.O.A. 11/12/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:12am @ 13/1/2020

Person Contacted:

Ankoon

Vehicle IN OUT

Date/Time

Action/Instruction Initial (X)

JTL 1549 - X

SHA 20855-CC4 / III/9015370 / Aph3

D.O.A: 00/08/2019

Dismantle - 17/1/2020 2.05pm

21/1/2020 Submit PRS report

ASS. REC. BY:

Rasm

REF:

III

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

JTL 1549

at Workshop m/s

Hua Chin

of SU Bukit Burok st. 23 # 02-02

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

JTL 1549

Yr Regn:

1

19

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

2

Make:

YAMAHA

c.c.

134

Colour:

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

32120

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Pmyu G0810K · 0106570

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90-17

R:

80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

11/2/19

D.O.I.

13/01/2020

11:12 am

Survey held at

HUA CHIN

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA REPORT

M. V. ?
(CEST)

RANGE 8 days - (3K-4K) / 5 days

RECEIVED 21 JAN 2020

16/1/2020

Date/Time, File Pass to?



Preli. Report



Final Report

1)

Date/Time, File Return to?

2) 21/1 - typist

Report Format:

Lump Sum / U/C /

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Wheel and

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL