

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION REPORT	
INCOPTION DEDOU	

AXA INSURANCE PTE LTD Ref: CS3/ASM20010892/Esf3e2

8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 21-10-2020

068811

- 11		
- 11		
- 11		
- 11		

Page No.:1 of 1

ATT	N : RICHARD AND	3	Code: ASM			
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBE 7320E	Veh. Inspected	SLK 3315Y		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	S0M02QXR	Excess (\$)	0.00		
	Assign From	RICHARD ANG	Assign Date	09/10/2020		
2.	. Vehicle Particulars & Condition					
	Make & Model	HONDA CIVIC	c.c	1597		
	Engine No.	HIDDEN	Year of Reg.	2017		
	Chassis No.	MRHFC5650GT000841	Colour	RED		
	Odometer	57713 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.		Coi	nditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	205/55 R16	HANKOOK	5 mm		
	L/H Front Tyre	205/55 R16	HANKOOK	5 mm		
	R/H Rear Tyre	205/55 R16	HANKOOK	5 mm		
	L/H Rear Tyre	205/55 R16	HANKOOK	5 mm		
1.		Desci	ription of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR O/S PORTION.			
5.		Ger	neral Information			
	Assistant Data	40/07/2020	In an act Data / This	00/40/2020 / 44.45 AM)		

	5.	General Information				
	1	Accident Date	18/07/2020	Inspect Date / Time	09/10/2020 (11:45 AM)	
ſ	5	Survey held at	8 KAKI BUKIT AVE 4 # 03-46 PREMIER			
		Repairer	GARAGE 13 PTE LTD			
ſ	5a.	a. Remarks				

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

Report Ref No. CS3/ASM20010892/Esf3e2

Inspected By

CHEN TSUE YEE

M. K. I. ALL COT

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.