

ASS. REC. BY:

REF: CS3/ASM20010892/Esf3

Special Instruction:

Surveyor: STEVE

ASSIGNMENT (Office)

From (Person): RICHARD ANG of AXA Date/Time: 9/10/2020 10:01 AM

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 3315Y Insured: GBE 7320E

at Workshop m/s Garage 13 Pte Ltd Tel: 63851171

of 8 kaki bukit ave 4 # 03-46 PREMIER

Policy No: Claim No: S0M02QXR

Sum Insured: Excess:

Make of Veh: D.O.A. 18-7-20
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 9-10-20 10.61A.M

Person Contacted: IRENE Vehicle ☒ IN OUT

Date/Time	Action/Instruction (X) Estimate
	SLK 3315Y- NA/INC19013464/z4 DOA :30/07/2019
	GBE 7320E- CC3/AIG18000774/K1ws3q2 DOA :10/01/2018