



SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S0M02V6Z
Reference	CS3/ASM20010893/R1sf3e2 
Loss Date	7 October 2020
Report Date	9 Oct 2020 8:41:47 AM
Request Date	9 October 2020
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for: Approve invoice

[Add Invoice](#)

Vehicle Information

Incident SMR6655Y
Vehicle
Registration #

Make TPVD

Model HONDA

Service Address

’, ’

Primary Contact/Insured

SURANI KHAIRIL SHAFIQ BIN
121 BEDOK NORTH ROAD, #08-161, 460121,
Singapore

Claim Handler

OH Vale

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2007390.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	4 November 2020
 LKKPreRepairInspection.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	4 November 2020
 AXA Immediate Advice - SMR 6655Y (TP) -.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 October 2020
 LKK SURVEYOR PHOTO.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	29 October 2020
 REPLY FROM TP.msg	Letters and Correspondence	Workshop	KUMAR Shailendra	9 October 2020
 SMR6655Y TP GIA.PDF	Letters and Correspondence	Workshop	KUMAR Shailendra	9 October 2020

 AME TP EMAIL.msg	Letters and TYPE Correspondence	Workshop	KUMAR Shailendra	9 October 2020
 FBK5332C INS GIA.PDF	Reports & Statement	GIA Report	KUMAR Shailendra	9 October 2020
 CLAMANT TP.pdf	Letters and Correspondence	Workshop	KUMAR Shailendra	9 October 2020
 PRI TP EMAIL PDF.pdf	Letters and Correspondence	Workshop	KUMAR Shailendra	9 October 2020