

ASS. REC. BY:

P. J. J.

REF:

CS3/ASM 20010893/RISF3

6717

EXPIRY: 2021/MAY

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMR 66554at Workshop m/s GARAGE 13of 25, KARI BUKIT PD HUB - 43 SYCAMOREInsured: AXA

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: SK

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMR 66554 Yr Regn: 2006Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CIVIC 1.8 L A c.c. 1799Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 170023 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMF016306S 208690

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or: ACENDA

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 07/10/2020 D.O.I. 20/10/2020Survey held at GARAGE 13Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit 2K

RANGE \$ 1.5K - \$ 2K/3 DAYS

Date/Time, File Pass to?

21/10/2020

1) TYPIST

Date/Time, File Return to?

2)

Rep. Format: PRS

Lump Sum / I.B.A. (\$) _____



Prel. Report



Final Report

Days Of Repair: 3Resurvey No. of Trip: -

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Estimated Cost:

Veh No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	671J

Vehicle No.:	SMR6655Y
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Oct 2020
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8LA
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	R18A11028231
Chassis No.:	JHMF163065208690
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$21,153.00
Original Registration Date:	12 Jun 2006
First Registration Date:	12 Jun 2006
Transfer Count:	1
Actual ARF Paid:	\$23,269.00

Intender PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intender COE Rebate Details

COE Expiry Date:	31 May 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$23,024.00
COE Rebate Amount:	\$2,822.00
Total Rebate Amount:	\$2,822.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Oct 2020

OK

Black



Merimen e-Claims



Used 2006 Honda Civic 1.8A VTi-



PARF/COE Reb

mart.com/used_cars/info.php?ID=928946&DL=2792

▶ Honda Civic 1.8A VTi-S (COE till 10/2021)

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price

\$9,888

Depreciation ⓘ

\$9,600 /yr

Reg Date

09-Nov-2006
(1yr 11days COE left)

Mileage

195,695 km (14k /yr)

Manufactured ⓘ

2006

Road Tax ⓘ

\$1,369 /yr

Transmission

Auto

Dereg Value ⓘ

\$5,846 as of today (change)

OMV ⓘ

\$20,324

COE ⓘ

\$28,376

ARF ⓘ

\$22,357

Engine Cap

1,799 cc

Power

103.0 kW (138 bhp)

Curb Weight ⓘ

1,219 kg

No. of Owners ⓘ

3

Type of Vehicle

Mid-Sized Sedan

Features

Original Condition. View specs of the Honda Civic (2006-2012)

d_cars/info_photos.php?ID=928946&CUR=4#photo



Sinc