

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1pc	Rear bumper	Grazed/Torn	2,232.82	2,232.82
2	1pc	Rear bumper retainer RH	Serviceable	50.75	-
3	1pc	Rear bumper chrome RH	Grazed	188.65	188.65
4	1pc	Rear sport rim RH	Grazed/Cut	2,291.55	2,291.55
5	1pc	Rear shock absorber RH	Serviceable	805.98	-
6	1pc	Rear fender RH	Dented/Warped	2,744.61	2,744.61
7	1pc	Rear windscreen glass with moulding	Necessary	998.21	998.21
8	1pc	Rear door RH	Dented/Warped	1,871.65	1,871.65
9	1pc	Rear door chrome moulding RH	Grazed	288.63	288.63
10	1pc	Rear door RH	Dented/Warped	1,882.74	1,882.74
11	1pc	Front door chrome moulding RH	Grazed	288.63	288.63
12	1pc	Front fender RH	Repair	771.40	-
13	1pc	Wing mirror assy RH	Broken	1,018.56	1,018.56
				15,434.18	13,806.05
		Less 10%		(1,543.41)	(1,380.60)
		Sub total		13,890.77	12,425.45
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1pc	Rear windscreen glass sealant	Necessary	100.00	80.00
2	1set	Rear bumper clip	Necessary	65.00	65.00
3	1set	Front door board clip	Necessary	45.00	45.00
4	1set	Rear door board clip	Necessary	45.00	45.00
5	1pc	Rear tyre RH	Serviceable	580.00	-
		Sub total		14,725.77	12,660.45
<u>LABOUR & MISC. CHARGES</u>					
1		Repair & replace damaged parts		1,200.00	1,000.00
2		Spray paint affected area		1,500.00	1,200.00
3		Remove & refix rear undercarriage	Not Necessary	260.00	-
4		Remove & refix rear trim board & garnish		120.00	80.00
5		Remove & refix rear windscreen glass		180.00	150.00
6		Remove & refix both door mechanism		300.00	240.00

Constant Appraiser Services

Vehicle No : SLK 6038C

Our ref : CAS/18-09/003

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
7		<u>LABOUR & MISC. CHARGES (CONT'D)</u>			
		Check wheel alignment (before & after repair)		240.00	200.00
			Grand total	18,525.77	15,530.45
Recommended cost of lump sum repair (To its pre-accident condition)					14,000.00


Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$14,000.00** on a contractual basis. Under normal circumstances, the repair period would be about **5 (Five)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA



SINGAPORE POLICE FORCE

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999



1720180824236

Report No: 1720190824236

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
24/08/2018 23:36

Video Report No.:

Station Diary No:
151

Informant's Particulars

Name of Informant: ABDUL NAJID BIN JEMANGIL			Address: NO. D 8/1 KG KOLAM AIR MUKIM 18 83500 PARIT SULONG JOHOR	
ID Type / ID No.: PASSPORT / A40273011			Contact No.:	
Nationality: MALAYSIAN			Home/Office: Mobile: 1067727274	
Sex: Male Age: 38 Date of Birth: 29/11/1979			Email:	
Race: Malay			Type of Informant: Driver	
Occupation: Truck Driver			Language: English Institution / School Name:	
			Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 24/08/2018 20:25	Type of Location: Straight Road
-------------------	----------------------------	--------------------	--	------------------------------------

Location:
Along Road 1
STEVENS ROAD

Beside Raffles Girl's School before the junction of Anderson Rd

Weather: Clear	Road Surface: Dry	Road Speed Limit:
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction		Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passengers
BHS3305	Truck				Slightly Damaged	0
SLK8038C	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

2 of 3
Case No: 17201084/2172

CONTINUATION OF REPORT

Name	ABDUL NAJID BIN JEMANGIL	ID No.	14971361
Related Vehicle	BHS3305 (Truck)	Contact No.	16672722
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	Unknown Driver	ID No.	NIL
Related Vehicle	SLK6038C (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 24/08/2018 at about 2025hrs, I was driving my vehicle BHS3305 along Stevens Road along the extreme right lane.

Later, I tried to do a left lane change, I felt an impact on the left side of my vehicle which I found out that a vehicle (SLK6038U) side swipe onto my vehicle (BHS3305). Subsequently, I went out of the vehicle, made a check and discovered that my vehicle was out of lane. I wish to inform that due to the collision, the other vehicle (SLK6038U) sustained a broken right side mirror. Subsequently, the police came down later to take down our particulars. I wish to inform that I did not record down the other driver particulars and I also do not have any in-car CCTV. I also wish to state that there was no injuries on all parties.

I am lodging this report as my vehicle is a foreign vehicle and as police advised me to do so.



**SINGAPORE
POLICE FORCE**



T/20180824/2172

Police Station Of Origin:
Bishan N.P.C.
20 Bishan Street 23 SINGAPORE 678767
Tel No: 1800-5529099

Report No: T/20180824/2172

CONTINUATION OF REPORT

Sketch Plan:

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474886 stating the report number as reference

Signature Of Officer Recording The Report:

E /

Sgt 2 PANG XIU KANG

Signature Of Informant:

Date/Time:

24/08/2018 23:36

Signature Of Interpreter:

Not applicable

Classification Of Case:

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

SN:061

Authentication Stamp

NP168

 SINGAPORE POLICE FORCE

SIGNATURE



**SINGAPORE
POLICE FORCE**



T/20180825/2004

1 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20180825/2004

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/08/2018 00:14	Vide Report No.: E/20180824/0194	Station Diary No.: 11
--	-------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: LEE MING JIE		Address: APT BLK 205 PETIR ROAD #12-605 SINGAPORE 670205	
ID Type / ID No.: NRIC NO / S8770707E		Contact No.: Home/Office: Mobile: 96625023	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 31	Date of Birth: 29/07/1987	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: PSA Operation Managers		Driving Licence Information: Class: 2B,2A,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/08/2018 20:25	Type of Location: Straight Road
Location: Along Road 1 STEVENS ROAD				
Before the junction of Stevens road and Anderson Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
BHS3305	Car				No Damage	0
SLK6038C	Car	VOLKSWAGO N	PASSAT CC 1.8T AT 3574H7	Grey	Slightly Damaged	1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLK6038C	AXA INSURANCE SINGAPORE PTE LTD	GA349665	10/05/2018	09/05/2019



**SINGAPORE
POLICE FORCE**



T/20180825/2004

2 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20180825/2004

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	ABDUL NAJID BIN JEMANGIL	ID No.	A40273011
Related Vehicle	BHS3305 (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE MING JIE	ID No.	S8770707E
Related Vehicle	SLK6038C (Car)	Contact No.	96625023
Hospital/Clinic	INTEMEDICAL 24 HR CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	24/08/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 24/08/2018 at about 2025hrs, I was driving my vehicle on the middle lane along Stevens road towards orchard road. I then stopped my vehicle (SLK6038C) before the stop line of the junction of Stevens Road and Anderson Road.

Before that, I observed that there was a truck (BHS3305) on the extreme right lane drove into my lane. Subsequently, the truck side swipe on my vehicle right side causing scratches on the whole right side and my right side mirror of my vehicle to drop off. I then asked him what happen which he told me that he wanted to make a right turn however the road was only to move straight. I then called for the police who advised me to lodge a police report as it is a foreign vehicle. I wish to inform that I have an in-car CCTV which recorded the whole accident. The traffic police took the in-car CCTV SD Card of my vehicle for the evidence.

I then went to see a doctor as I felt pain on my neck and left elbow. I was then given a 3 days MC. I am lodging this report for insurance claims and as advised by the police as it is a foreign vehicle.



SINGAPORE
POLICE FORCE



T/20180825/2004

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

3 of 4
Report No. T/20180825/2004

CONTINUATION OF REPORT

CONTINUATION OF REPORT



SINGAPORE
POLICE FORCE



T/20180825/2004

4 of 4

Report No. T/20180825/2004

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 PANG XIU KANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 25/08/2018 00:14
Officer In Charge Of Case: TP / GIT / SI YEO CHUN JIAN Contact No.: 65476213	Classification Of Case: SN 061
Authentication Stamp NP168	 SINGAPORE POLICE FORCE SIGNATURE