COMFORTDELGRO ENGINEERING PTE LTD

LKK

_	REPAIR ES	TIMATE		
DATE:	09/10/20	3P INSURANCE:	AIG	
MODEL:	HYUNDAI IONIQ	SURVEYOR: _		
VEH NO.:	SHD4761U	MVA:	TOKE MA	

ART NO.	brannen.	QTY	LIST PRICE	REMARKS	22.14
	DESCRIPTION	1		\$418.30	31464
	Front Bumper / DK	1		\$35.00	X
	Front Bumper Bracket Top LH 7 X AIM	1		\$28.00	22.40
	Front Bumper Bracket LH	1		\$188.00	150.40
200 0 0 0	Front Bumper Centre Moulding / (VI	1		\$186.90	149.52
	Front Bumper Grille LH / (M)	1		\$642.50	514.00
	Day Light LH / (NT) Front Bumper Clips / NC	10		\$22.00	17.60
	Headlamp LH / (V1	1			1594.92
	Headlamp Support Panel Assy X AIM	1		\$949.30	
	Headlamp Support Failer Assy X 74"	1	si 1		392-56
	Front Fender LH / 00 Front Wheel Hub Cap LH / (UT	1	₽		277-12
	Front Fender Shield LH 1 X MM	1	A	\$114.70	
	Front Fender Shield LH	1		\$26.60	21.38
	Emblem Blue-Drive LH / / / (1		\$1,797.20	1437-76
1	Front Door LH / 00	1		\$65.76	×
•	Front Door Hinge Upper LH \propto \wedge \wedge \wedge	1	*	\$65.76	×
•	Front Door Hinge Lower LH A 14 M		8 _ ·	\$72.98	The same of the sa
	Front Door Check LH X MM	1		\$78.00	<
F	Front Door Outer Handle LH X 14/11	1		\$290.00	132.90
F	Rocker Panel Outer Garnish LH 🔏 🖊 🖟	1	I m 1	Q200 ,00	132.00
					5144-20 V
- 1	SPARE PARTS SUB TOTAL			\$7,811.75	31447
	LESS 20%		1 2 2	\$1,562.35	T 4, 21 4
	DISCOUNTED SPARE PARTS TOTAL			\$6,249.40	-
	DISCOUNTED				col defen
- special	74	1		198 \$216.00	Nett 50% defen
Fr	ront Tyre LH / 7/1	1		\$100.00	Nett
Fr	ront Fender Advertisement LH / IPC	1	9 B 9 5	\$75.00	Nett
Fr	ront Door Comfort Logo LH			\$100.00	Nett
Fr	ront Door Advertisement LH / ///(1		• 100.00	383 L
1	*		<u>g.</u>		1
	DISCOUNTED SPARE PARTS & NETT TOTAL		* *** ×	\$6,740.40	
	DIGGGG		a -		
		= -	= 1	\$1,000.00	960
Pa	anel Beating		(2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	\$900.00	100
Spi	ray Painting	a if the c		\$120.00 5	ĥ
Re	move/Refix Door Assy			~	1
	neel Alignment		100 S	\$90.00 60	
	eck Wiring			\$50.00	,011.
Crit	eux mining		= -		1900 v = 7417-20
	LABOUR TOTAL		N N	\$2,160.00	-42000

Page 1 of 8 Hyundai Sonata (Front)

CH IND		DESCRI	PHON		OTY LIST P	RICE PE	uanks
			ESTIMA	TE TOTAL		\$0	,900.40
a ia an i	pleiol a chies can		ual inspection of	the shove ve	hicle. The fina	I repair quant	um wil

prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company

LKK Auto Consultants hence notify

- the Repairer of the following: To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve CLKK) WIL Mil 9/10/10, 5-11pm PIP Ny Bef Spy 4 dys