

Our Job Ref No 305427345
Date : 15.10.20

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax : _____
Attn : Mr STEVE
Vehicle Reg No. SHD3314J CTPL 10.10.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG --- SMF6504M
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$4,605.32
 - (b) Labour Charges \$1,370.00
 - Total for Part-By-Part Repair Cost** \$5,975.32
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Steve
Date : 15/10/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305427345
 REGN NO : SHD3314J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 24.10.2018
 DATE/TIME IN : 10.10.2020 10:05
 ACCIDENT DATE : 10.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1	430.90	20.00	344.72	/	DR
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60	/	MC
0003	04-01-0104-3918-G	IONIQVC BRACKET-FR BUMPER	1	28.00	20.00	22.40	/	DR
0004	04-01-0104-2971-G	IONIQVC BRACKET-FR BUMPER	1	35.00	20.00	28.00	?	
0005	04-01-0104-2361-G	IONIQV1-3 MOULDING-FRONT	1	188.00	20.00	150.40	/	CUT
0006	04-01-0104-2417-G	IONIQVC MOULDING-FRT BUMP	1	85.10	20.00	68.08	X	
0007	04-01-0104-2915-G	IONIQV1-3 LAMP ASSY-HEAD	1	1,993.65	20.00	1,594.92	/	CUT
0008	04-01-0104-4991-G	IONIQV1-3 LAMP ASSY-DAY R	1	642.50	20.00	514.00	/	CUT
0009	04-01-0104-0633-G	IONIQV1-3 MOULDING-FRONT	1	93.60	20.00	74.88	/	CUT
0010	04-01-0104-0573-G	IONIQVC PANEL-FENDER RH#	1	588.80	20.00	471.04	X	R
0011	04-01-0104-3913-G	IONIQVC EMBLEM-BLUE DRIVE	1	26.60	20.00	21.28	X	✓ Part Taken
0012	04-01-0104-2934-G	IONIQVC GUARD ASSY-FRONT	1	114.70	20.00	91.76	X	
	S	Fit Bumper Reinforcement				\$1,075.10		
	S	Fit Support Panel				\$949.30		
JOB NATURE	S	Fit Bumper Grille Lower				\$186.90		
						SUB-TOTAL	:	3,399.08

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427345
REGN NO : SHD3314J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.10.2018
DATE/TIME IN : 10.10.2020 10:0
ACCIDENT DATE : 10.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

00 20-05	FRT FENDER ADVERTISMENT LOGO RH		100.00	/	nec
0001 L	PANEL BEATING (repair Bonnet)	800.00	220 640		
0002 23-502	SPRAYPAINT ON AFFECTED AREA	650.00	600		
0003 17-01	CHECK ALL LIGHTING	50.00	30		
0004 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	X		

SUB-TOTAL : 1,650.00

TOTAL : 5,049.08

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Steve CLKK) WML Pu
12/10/20, 9.30 am
3 days
P/P
My Bal sy

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 14.10.2020
Time: 15:05:14
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427345
REGN NO : SHD3314J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.10.2018
DATE/TIME IN : 10.10.2020 10:05
ACCIDENT DATE : 10.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1	430.90	20.00	344.72
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60
0003	04-01-0104-3918-G	IONIQVC BRACKET-FR BUMPER	1	28.00	20.00	22.40
0004	04-01-0104-2971-G	IONIQVC BRACKET-FR BUMPER	1	35.00	20.00	28.00
0005	04-01-0104-2361-G	IONIQV1-3 MOULDING-FRONT	1	188.00	20.00	150.40
0006	04-01-0104-2417-G	IONIQVC MOULDING-FRT BUMP	1	85.10	20.00	68.08
0007	04-01-0104-2915-G	IONIQV1-3 LAMP ASSY-HEAD	1	1,993.65	20.00	1,594.92
0008	04-01-0104-4991-G	IONIQV1-3 LAMP ASSY-DAY R	1	642.50	20.00	514.00
0009	04-01-0104-0633-G	IONIQV1-3 MOULDING-FRONT	1	93.60	20.00	74.88
0010	04-01-0104-0634-G	IONIQVC GRILLE-FRONT BUMP	1	186.90	20.00	149.52
0011	04-01-0104-3913-G	IONIQVC EMBLEM-BLUE DRIVE	1	26.60	20.00	21.28
0012	04-01-0104-0641-G	IONIQVC CARRIER ASSY-FRON	1	949.30	20.00	759.44
0013	04-01-0104-2419-G	IONIQVC BEAM COMPLETE-FR	1	1,075.10	20.00	860.08

COMFORTDELGRO ENGINEERING PTE LTD

Date: 14.10.2020

REPAIR ESTIMATE

Time: 15:05:14

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427345
REGN NO : SHD3314J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.10.2018
DATE/TIME IN : 10.10.2020 10:0
ACCIDENT DATE : 10.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 4,605.32

JOB NATURE

0000 20-05	FRT FENDER ADVERTISMENT LOGO RH	100.00
0001 L	PANEL BEATING(repair Bonnet)	640.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	600.00
0003 17-01	CHECK ALL LIGHTING	30.00

SUB-TOTAL : 1,370.00

TOTAL : 5,975.32

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :