

Like

AIG

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 10.10.2020
Time: 13:52:33
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427345
REGN NO : SHD3314J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.10.2018
DATE/TIME IN : 10.10.2020 10:05
ACCIDENT DATE : 10.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1	430.90	20.00	344.72	/	DR
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60	/	MC
0003	04-01-0104-3918-G	IONIQVC BRACKET-FR BUMPER	1	28.00	20.00	22.40	/	DR
0004	04-01-0104-2971-G	IONIQVC BRACKET-FR BUMPER	1	35.00	20.00	28.00	/	* MC DR /
0005	04-01-0104-2361-G	IONIQV1-3 MOULDING-FRONT	1	188.00	20.00	150.40	/	CUT
0006	04-01-0104-2417-G	IONIQVC MOULDING-FRT BUMP	1	85.10	20.00	68.08	X	MC / BR
0007	04-01-0104-2915-G	IONIQV1-3 LAMP ASSY-HEAD	1	1,993.65	20.00	1,594.92	/	CUT
0008	04-01-0104-4991-G	IONIQV1-3 LAMP ASSY-DAY R	1	642.50	20.00	514.00	/	CUT
0009	04-01-0104-0633-G	IONIQV1-3 MOULDING-FRONT	1	93.60	20.00	74.88	/	CUT
0010	04-01-0104-0573-G	IONIQVC PANEL-FENDER RH#	1	588.80	20.00	471.04	X	R
0011	04-01-0104-3913-G	IONIQVC EMBLEM-BLUE DRIVE	1	26.60	20.00	21.28	X	MC / MC
0012	04-01-0104-2934-G	IONIQVC GUARD ASSY-FRONT	1	114.70	20.00	91.76	X	NM

JOB NATURE

2749.72
2836.78

SUB-TOTAL : 3,399.08

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 10.10.2020
Time: 13:52:33
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427345
REGN NO : SHD3314J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.10.2018
DATE/TIME IN : 10.10.2020 10:0
ACCIDENT DATE : 10.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0000 20-05	FRT FENDER ADVERTISMENT LOGO RH	100.00	/	100.00
0001 L	PANEL BEATING (repair Bonnet)	800.00		320 640
0002 23-502	SPRAYPAINT ON AFFECTED AREA	650.00		600
0003 17-01	CHECK ALL LIGHTING	50.00		30
0004 20-00	TUFF COAT ON AFFECTED PARTS.	50.00		X
SUB-TOTAL		: 1,650.00		

TOTAL : 5,049.08

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Steve CLKK) WML Pu
12/10/20, 9.30 am

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

322 days

P/P

My Del sy