

NAZ

REF:

AXA

ASSIGNMENT

Date: _____

Assigned to: _____

Type: NS / TP / RES / LOO / RES / EVA / INV / MV

To inspect Vehicle NO: _____

To inspect Stop ID: _____

To inspect: _____

To inspect: _____

To inspect: _____

To inspect: S9M01G23

To inspect: _____

To inspect: _____

To inspect: _____

To inspect: _____

To inspect: _____

To inspect: _____

To inspect: 5.5K(est)

To inspect: _____

To inspect: _____

To inspect: _____

To inspect: _____

To inspect: _____

To inspect: _____

To inspect: _____

Veh No: SJQ 5827R Yr Reg: 18 MAY 2009Type: M.Cer / M.Cycle / BUS / Van / Lorry / Taxi / Private Motor

Truck / Trailer or _____

Make: HYUNDAI AVANTEColour: SILVERSe Reading: N/A

Engine: _____

Chassis: KMH04Y1BR9U760984Gen. Cond. Good / Fair / Poor / BurntSteering: Harder / Jammed / Locked / Burnt orBrake: Harder / Jammed / Locked / Burnt orWheel: OK / Slightly / STD / AIR / orTire Size: 11Tire: 195 165 R15

BS / COT / EXHORA / GY / PS / FL / ZA / MC / O / H / S / U / P / R / S / U / H

Tire: YOKO or CONTINENTAL / KMH0

Tire: _____

Tire: 4 mmTire: 4 mmTire: 5/3/2019Tire: 18/10/2020Tire: ETHOZ TAMPWESTire: Front / Rear / O/S / N/S / U/C / Not / orTire: U/C / Chassis frame / Body structure / affected / due to / or

11/06/21 Submit Extensive total loss report.

Investigation \$500/-

Days Of Repair: _____

11/06 Typist: _____

11/06 Typist: _____

SMART CLAIMS - TL/E

11/06/21

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transport: _____

Add Fee: _____

Add Fee: _____

Add Fee: _____

Add Fee: _____