


ASS. REC. BY: P. Ram REF: CC3/A1420011000/RIGS3 775h
LOG # P144: 2024/SEP

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD (P) / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKP6913L
at Workshop m/s Volksvagen
of 247, ALEXANDRA RD
Insured: A14
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SKP6913L Yr Regn: 2014 / SEP
Type: (C) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Volksvagen Golf A71.4T c.c. 1395
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 73315 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: NVW222ANZF026432
Gen. Cond: Good / (P) / Poor / Burnt
Steering: (P) / Jammed / Leaked / Burnt or _____
Brake: (P) / Jammed / Leaked / Burnt or _____
Modi: Nil / (C) / STD A/Rim or _____
Tyre Size: F: 225/40ZR18
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / (C) / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 10/10/2020 D.O.I. 15/10/2020
Survey held at Volksvagen
Des. of Damages: Frt / (C) / R / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: 42K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	Repair find illk

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____
Report Format: _____
Lump Sum / I.B.A. (\$) _____
Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)
Survey Fee: _____
Transportation: _____
S + RS. \$ _____
Photos _____
Others _____
TOTAL _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	775G
Vehicle No.:	SKP6913L
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT 5G13GZ SR HID
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	CX5215672
Chassis No.:	WVWZZZAUZFW026432
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,710.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	1
Actual ARF Paid:	\$8,794.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2024
PARF Rebate Amount:	\$5,716.00

COE Expiry Date:	29 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,000.00
COE Rebate Amount:	\$24,507.00
Total Rebate Amount:	\$30,223.00

The information contained herein is correct as at 16 Oct 2020

OK

Silver



Volkswagen Golf 1.4A TSI

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$42,600

Depreciation ? \$9,940 /yr
View models with similar depre

Reg Date 29-Oct-2014
(4yrs 12days COE left)

Mileage 122,016 km (20.4k /yr)

Manufactured ? 2014

Road Tax ? \$624 /yr

Transmission Auto

Dereg Value ? \$28,521 as of today (change)

OMV ? \$19,226

COE ? \$62,000

ARF ? \$5,000

Engine Cap 1,395 cc

Power 90.0 kW (120 bhp)

Curb Weight ? 1,249 kg

No. of Owners ? 1

Type of Vehicle Hatchback

Features

Responsive 1.4L TSI Engine, 120Bhp, 7 Speed DSG (A). Bluemotion Technology. Steering Control. Auto Headlamps. Rain Sensors. Electric Brake/Brake Hold. View specs of the Volkswagen Golf (2012)

Accessories

Sports Rims, Premium Leather Upholstery, Factory Fitted Audio System. Retractable Side Mirrors With Indicators. Multi Function Steering Wheel Control