




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20011037/Etd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 29-10-2020	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLA 8692C	Veh. Inspected	SHC 1380K
	Policy No.	5098669905-02	Coverage (\$)	0.00
	Claim No.	MT/1106278-002	Excess (\$)	0.00
	Assign From		Assign Date	12/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KMHC851CVKU107521	Colour	BLUE
	Odometer	253204	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	CONTINENTAL	5 mm
	L/H Front Tyre	195/65 R15	CONTINENTAL	5 mm
	R/H Rear Tyre	195/65 R15	CONTINENTAL	5 mm
	L/H Rear Tyre	195/65 R15	CONTINENTAL	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/10/2020	Inspection Date	12/10/2020
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	