

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD Rei				NS/INC20011041/Eyd3s2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556				3-11-2020		
4		Delias Bestivolese		NC4		
1.	Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SKS 9427M					
	Policy No.	5102642370-01	Coverage		0.00	
	Claim No.	MT/1106168-002	Excess (0.00	
	Assign From	W171100100-002	Assign D		12/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c	onation	1798	
	Engine No.	HIDDEN	Year of R	Rea.	2017	
	Chassis No.	JTDKB3FU003563093	Colour	-3	BLUE	
	Odometer	446088	Steering		IN ORDER	
	Brakes	IN ORDER	Modificat	tion	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	GOODYE	AR	5 mm	
	L/H Front Tyre	195/65 R15	GOODYE	AR	5 mm	
	R/H Rear Tyre	195/65 R15	GOODYE	AR	5 mm	
	L/H Rear Tyre	195/65 R15	GOODYE	AR	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	09/10/2020	Inspection	on Date	12/10/2020	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	1					

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: