

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 305427841  
Date : 13 10 2020  
Time of Fax: \_\_\_\_\_

Via Fax : Email  
Your Insured: SME 6474X  
Date of Acc : 12 10 2020

Attn: Motor Claims Department

Dear Sirs

Ag Abia

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH**

B 4387C

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident \_

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

◆ Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} Fax no. 6546 8156
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
➔ <b>Lim Tien Siong</b>	Tel: 6214 8398 or HP: 9635 8546	
➔ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
◆ Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

**Lim Tien Siong**

for Vice President  
Crash Repairs & Claims Recovery

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.10.2020

## REPAIR ESTIMATE

Time: 14:38:38

Page: 1

Ang Asia

12

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305427841  
 REGN NO : SHB4387C  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 06.12.2018  
 DATE/TIME IN : 13.10.2020 12:15  
 ACCIDENT DATE : 12.10.2020

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0302-2282-G	REAR BUMPER	1	458.60	25.00	343.95
0002	04-01-0302-2287-G	REAR BUMPER CENTER-Black	1	552.60	25.00	414.45
0003	04-01-0302-2286-G	REAR BUMPER TOW COVER	1	82.70	25.00	62.02
0004	04-01-0302-2288-G	REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10
0005	04-01-0302-2267-G	REAR BUMPER CLIPS	10	22.00	25.00	16.50
0006	09-01-0302-2005-A	REVERSE SENSOR	1	135.70	<del>2.50</del>	135.70

SUB-TOTAL : 1,211.72

## JOB NATURE

0000	PB	PANEL BEATING				350.00
0001	SP	SPRAYPAINT CHARGE				250.00
0002	L	R/I REVERSE SENSOR				120.00

SUB-TOTAL : 720.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.10.2020

REPAIR ESTIMATE

*Ag Asia*

Time: 14:38:38

Page: 2

*R*

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305427841  
REGN NO : SHB4387C  
MILEAGE : 000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID  
DATE OF REGN : 06.12.2018  
DATE/TIME IN : 13.10.2020 12:1  
ACCIDENT DATE : 12.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

*Lims*

TOTAL : 1,931.72

\_\_\_\_\_  
MVA NAME & SIGNATURE

DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO