



Service Request Details

Claim	S0M02VCC
Reference	CS3/ASM20011055/Evd3 
Loss Date	10 October 2020
Report Date	12 Oct 2020 4:04:23 PM
Request Date	12 October 2020
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident GBD1158C
Vehicle
Registration #

Make TPVD

Model NISSAN

Service Address

'''

Primary Contact/Insured

KUN KAY HONG
21 FORT ROAD, #11-03, 439089, Singapore
97377787
PL@ANIKA.SG

Claim Handler

OH Vale
6568804897

Additional Instructions

2

[Messages](#)
[Invoices](#)
[History](#)
[Documents](#)
[Assessment](#)
[Metrics](#)
[Notes](#)

Document Type

Document SubType

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2007112.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2020
 LKKPreRepairInspection.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2020
 Resurvey photo-1.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2020
 LKK photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 October 2020
 Immediate Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 October 2020
 photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	14 October 2020
 INSRD GIA REPORT.PDF	Reports & Statement	GIA Report	OH Vale	13 October 2020

NAME	TYPE	SUB-TYPE	AUTHOR	2020 DATE UPLOADED
 REPLY FROM TP.msg	Letters and Correspondence	Workshop	KUMAR Shailendra	12 October 2020
 CLAIMANT TP.pdf	Letters and Correspondence	Workshop	KUMAR Shailendra	12 October 2020
 PRI TP EMAIL PDF.pdf	Letters and Correspondence	Workshop	KUMAR Shailendra	12 October 2020
 GBD1158C TP GIA.PDF	Reports & Statement	GIA Report	KUMAR Shailendra	12 October 2020
 PRI TP EMAIL.msg	Letters and Correspondence	Workshop	KUMAR Shailendra	12 October 2020