



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20011069/Byd3e2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 03-11-2020



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |             |                       |            |
|---------------------|-------------|-----------------------|------------|
| <b>Insured Veh.</b> | SLT 5073J   | <b>Veh. Inspected</b> | SMQ 9697L  |
| <b>Policy No.</b>   |             | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | C10007501   | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | IVY RATILLA | <b>Assign Date</b>    | 13/10/2020 |

### 2. Vehicle Particulars & Condition

|                         |                         |                     |            |
|-------------------------|-------------------------|---------------------|------------|
| <b>Make &amp; Model</b> | TOYOTA C-HR HYBRID 1.8S | <b>c.c</b>          | 1797       |
| <b>Engine No.</b>       | HIDDEN                  | <b>Year of Reg.</b> | 2019       |
| <b>Chassis No.</b>      | ZYX102163286            | <b>Colour</b>       | YELLOW     |
| <b>Odometer</b>         | 59096                   | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER                | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | FAIR                    |                     |            |

### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 215/60 R17  | DAVANTI     | 6 mm           |
| <b>L/H Front Tyre</b> | 215/60 R17  | DAVANTI     | 6 mm           |
| <b>R/H Rear Tyre</b>  | 215/60 R17  | DUNLOP      | 6 mm           |
| <b>L/H Rear Tyre</b>  | 215/60 R17  | DUNLOP      | 6 mm           |

### 4. Description of Damages

|  |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--|

### 5. General Information

|                       |  |                        |            |
|-----------------------|--|------------------------|------------|
| <b>Accident Date</b>  | 03/10/2020   | <b>Inspection Date</b> | 13/10/2020 |
| <b>Survey held at</b> | TEAM AUTOPRO PTE LTD<br>160 SIN MING DR<br>#01-14 SIN MING AUTO CITY<br>SINGAPORE 575722 |                        |            |

### 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>6 Working Days</b> |
|-------------------------------------|-----------------------|