

AG- (Lisum) JU

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 13.10.2020
Time: 17:14:42
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427843
REGN NO : SH 9589S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 26.05.2016
DATE/TIME IN : 13.10.2020 15:55
ACCIDENT DATE : 13.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	/	DD
0002 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	X	
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	/	RC
0004 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	/	AK
						SUB-TOTAL :	1,134.80

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 20-05	RENEW ADVERTISEMENT STICKER-BUMPER	50.00	X
0003 20-05	RENEW ADVERTISEMENT STICKER-FENDER	200.00	X
0004 L	REMOVE/REFIX REVERSE SENSOR ASSY	80.00	X
		SUB-TOTAL :	930.00

Stem (CLKK) ml M
14/10/20, 19.10.20
2 dys
L/S
My AL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 13.10.2020

Time: 17:14:42

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305427843
REGN NO : SH 9589S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 26.05.2016
DATE/TIME IN : 13.10.2020 15:5
ACCIDENT DATE : 13.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,064.80

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

FORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

69 Loring Drive Singapore 508990

181 Sin Ming Drive Singapore 575717

65 Chandler Road Singapore 600546

24 Serangoon Singapore 758156

7 Serangoon Road Singapore 728791

501 Vishnu Industrial Park A Singapore 768735

Member of COMFORTDELGRO

Date/Time 13.10.2020 17:11

Page : 1

Am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO. 305427843

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO SH 9589S	MILEAGE
MAKE HYUNDAI	FUEL E 1/2 F
MODEL I-40	DATE/TIME IN 13.10.2020 15:55
YR OF MANUF 26.05.2016	TARGET DATE
CHASSIS CODE KMILB41UMGU089924	COMPLETION DATE/TIME


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 13.10.2020
NATURE: 3P 13.10.2020

S/NO LABOR CODE

DESCRIPTION



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SH 9589S

JU AIG

Vehicle No.:

SH 9589S

Service Advisor

Signature/Date

Name of Service Advisor

Date

ned to Service Reception upon collection

To be kept by Security Guard