

Estimated Cost
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No
 at Workshop m/s
 of
 Insured
 Policy No
 Claim No
 Sum Insured Excess
 (Client's Record)
 Make of Veh

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal or Market Value

IDAC Accident Report

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est Repairs

days Res: Yes or No

Lum Sum

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Veh No GBH5579Z at Regn 2018, July
 Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Fiat Doblo C.R. 1598

Colour: Yellow A/C Insured / Std / NI / NA

Sp Reading 87790 T/Radio: Insured / Std / NI / NA

Eng/No

C/No

Gen Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal 86 mm

R/Bal 86 mm

L/Bal 86 mm

L/Bal 86 mm

D.O.A 7/10/20

D.O.I 09/10/20

Survey held at T.K.

Des of Damages: Frt Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
 TP Direct Asic Independent

28/4/21 Adrian confirmed LS \$12,050 (Red 5705.30, 32%)

MV

PV

Nett

Attach paint protection invoice into report

Date/Time File Path to



: Prel. Report

to



: Final Report

Date/Time File Path to

29/4/21-Typist

29/4/21-Typist TP

LS \$12,050

Days Of Repair: 11

Resurvey No. of Trip: 1

Total Fees:



Site Insp \$



Intervisys \$



Fees in total \$



Total fees \$

Survey Fee:

Transportation

S + FS \$

Labour

Other

7x15=105

105+170

50

50

122

80

577