

REF: CS1/LPM 20011095 / G v f3

Special Instruction:

From (Person): An Lu Tyng of LPC Date/Time: 13-10-20 3:48pm
Estimated Cost: _____ Bill to: _____

2/Sum: \$ 16,100.00

Third Parties:

Claimant:

Surveyor:

Workshop: Yee Auto Service

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJR 5318m Insured: WRS 3488

at Workshop m/s Yee Auto Service Tel: 6457 5768

of BLK 15, 1A01-107 Sin Ming Industrial Estate

Policy No: _____ Claim No: 18/19/19/VPD2/295935

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3.6.2019
(Client's Possession)

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 12/12/22 Confirmed with Final Fig , days (Red \$ / %; Original 9 days)

Date/Time: 19/10/20 Submit Final Fig LS \$3200, 5 days (Red \$12,900/80 %; Original days)

[illegible]

Para(1) : Parts found not replaced	(To highlight R or UB , LR , Etc)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____